

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13327B

Date In:	25 APR 26	Author:	DMCGINLEY
Promised Date:	31 MAY 26	Stock No:	11387
:	:	Year:	2025
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	REFLECTION FW
:	MIDDLEBURY, IN	Model:	311BHS
Postal/Zip:	46540	Miles/Hrs:	0
Phone#(res):	888-825-2820	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	6/8- text for video of
Purchased Date:	07 APR 26	:	:
Delivery Date:	24 APR 26	:	:
InService Date:	:	:	:
Serial#:	573FR3821S9929726	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Lp bottles are no    W    1020    GRAND
        good neither will fill
        CAUSE:      FOUND WHILE DOING FINISH PREP- THE TANKS
        WILL NOT TAKE PROPANE
        CORRECTION: TANKS NEED TO BE REPLACED. 30# TANKS
WARR    COMPLAINT:  WARRANTY REPAIR 2 - dining shade here to W    1020    GRAND
        be installed
        CAUSE:      Bad shade 2nd replace first one was not
        correct size
        CORRECTION: So whoever had tried I stalling first
        replacement used screws that did not
        hold well so removed then reinstalled
        brackets with proper type screw then
        installed new shade this took awhile
        trying to get aligned correctly but it's
        now good and works like it should  SEE
        RO: 12095B FOR LABOR- JUST NOTING ON
        THIS WORK ORDER AS THE TECHNICIAN WAS
        NOT ABLE TO GRAB THE OTHER WORK ORDE.R
6        COMPLAINT:  FOUND DURING THE SHOWTHRU- THE WINDOW    W    1020    GRAND
        ABOVE THE COOKING STOVE DOES NOT OPEN
        CAUSE:      on off door side window above cooking
        stove doesn't open the slide glass frame
        catching again frame of fixed window
        frame pics taken of tags and wear marks
        on framework
        CORRECTION: needs a new window....
7        COMPLAINT:  Customer states valance above dinette    W    1020    GRAND
```

Continued on page 2

Work Order : 13327B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                window fell off.
                                CAUSE:      SCREWS STRIPPED
                                CORRECTION: REINSTALLING

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 899003000311 30# PROPANE CYL      W-1020      1      115.09      115.09
6      82200654      WINDOW 8800 DW 24 X 15 G W-1020      0      88.91      0.00
6      822080424      WINDOW TRIM RING ONLY 88 W-1020      0      13.14      0.00

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR      W-1020      0.00      140.00      0.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.00      140.00      0.00
6 WARR      MANUFACTURER WARRANTY JS      W-1020      0.50      140.00      70.00
7 Z992      MISC LABOUR CODE (WARR      W-1020      0.00      140.00      0.00
6 WARR      REPLACE WINDOW      W-1020      0.00      140.00      0.00

```

```

*****
Job # Excode      Description EXTRAS      bill to      Qty      Price      Total
*****
6 FRT      FRT FOR LINE 6      W-1020      1.00      30.27      30.27
6 FRT      FREIGHT FOR TRIM RING W-1020      1.00      19.01      19.01

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1020      115.09      70.00      0.00      49.28      0.00      234.37
                                Totals      115.09      70.00      0.00      49.28      0.00      234.37

```

&k2S
&k0S