



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67 18
Promis Date: 06 MAY 22

CUSTOMER WORK ORDER

WO #: 67298

Customer: 5741 - HARSHA, MICHAEL L.
- 812-787-0250

Tag:

Author: BH

Location: 0506 DELIVERY

Stock #: 11066

Stock Desc: 2022 TT KEYSTONE
SPRINGDALE 311RE

Chassis #: 4YDTSGR21N3104178

Serial #: 4YDTSGR21N3104178

Mileage:

Licence:

Invoice #:

Date In: 02 MAY 22

Promised: 06 MAY 22

Date Sched:

Completed: 30 APR 22

Warr. Date: 30 APR 22

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CORRECTION: SPAIR TIRE HAS O AIIT IN IT, NO WINTERIZER KIT ON WATER PUMP, WATER PUMP WILL NOT HOLD PUERSHER , TV NOT PICKING UP CHANELS,
water pump, check for water leaks, pull water pump and check check valve in water pump will not hold letting water back flow, change water pump as per DH, install water filter in line with pump, mark and put old pump and give to BH, install winterize valve at pump
check tires lug nuts, lights, brakes, breakaway, run LP drop test, check furnace water heater, micro wave, refer porgram TV, and test, raído, range fireplace, dewinterize, roof,

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JP	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 D	1.00	N/C	N/C
385311641	310 WATER VALVE - SEALAND	1.00	N/C	N/C
30910	30910 Fresh Water	1.00	N/C	N/C
28300	FLOJET WATER PUMP	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #SWAP - Internal

COMPLAINT: SWAP CUSTOMER'S HITCHWORK

CORRECTION: SWAPED CUSTOMERS HITCHWORK. RESET HITCH HIGHT AND HOOKED UP TO NEW TRAILER. ADJUSTED AS NEEDED.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #SWAP: 0.00

Job #1 - Internal

COMPLAINT: SWAP TV FROM TRADE BEDROOM

CORRECTION: dead bolt locked had to find keys Donnie had them, locking screw on mount in trade is striped, get screw out and remove TV, remove mount, take to new unit, this mount will not work in this location , find Dnnie, get new mount from parts, have to cut board to mount too wall so I can mount to boaed, mount TV to mount



Customer #: 5741
HARSHA, MICHAEL L.





Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Subtotal for Job #1:			0.00

Job #2 - Internal

COMPLAINT: INSTALL SECOND AC IN BEDROOM

CAUSE: unit has barrow ceiling

CORRECTION: peel sealer from vent, remove vent, cover screw holes with roof repair tape, put upper AC unit on roof and position, install plenem mark batting strips, remove plenem pull down batting strip and cut for ac fit, finish installing AC, wire up and test, tape of around AC and fill gap from barrow ceiling with silacone, clean up and pull out
AC dometic M# B57915.XX1JO SER # 14793116

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Parts Part #	Description	Qty	Price	Total
2791	CEILING KIT - BRIS	1.00	N/C	N/C
2792	#B57915.XX1JO 13.5	1.00	N/C	N/C
38-9089	QUICK ROOF EXTREME 6" X 25"	1.00	N/C	N/C
Subtotal for Job #2:				0.00

Job #WALK - Internal

COMPLAINT: WALK THRU

CORRECTION: SET UP CAMPER INWALK THRU AREA.DID WALK THRU AND PUT LEVELS ON CAMPER HOOKED UP AND DID BRAKE CONTROL.
Estimated Amount: 180.00

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Subtotal for Job #WALK:			0.00

Job #3 - Warranty

COMPLAINT: CHECK VALVE IN WATER PUMP FAILED

CORRECTION: REPLACE WATER PUMP. FOUND WORKING FINE NOW

Labor				
Code	Description		Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER		JP	45.00
Parts				
Part #	Description	Qty	Price	Total
186592	(KEYSTONE) FLOJET	1.00	46.43	46.43
Subtotal for Job #3:				91.43



W/O: 67198
Promised Date: 06 MAY 22

Parts Total:	46.43
Labour Total:	45.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	91.43

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 13 May 2022



Customer #: 5741
HARSHA, MICHAEL L.

