

Claim Response

Claim: C3091206

Non-Warranty Goodwill Adjustment

Last Modified byGrimS

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3091206	67324	5/10/2022	5/10/2022	4YDT28R29K7241069		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	7/20/2018

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
			1.00	0.00	0.00	15.00	0.00	0.00	0.00	0.00	Approved

Component Model: 6020

Component Serial Number: N 17 43

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442K	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B PART#380444 Cause: KEYSTONE LP REGULATOR RECALL Correction: FOUND REGULATOR TO BE GOOD DIDNT NEED ONE		0.30	0.30	45.00	0.00	1	0.30	Approved

Submitted parts & subLet 0.00
 Submitted labor & subLet 45.00
 Submitted freight: 0.00
 Tax: 0.00
 Total Submitted: 45.00

Approved parts & subLet 0.00
 Approved labor & subLet 45.00
 Approved freight: 0.00
 Tax: 0.00
 Total approved: 45.00