

Claim Response

Claim: C3093552

Non-Warranty Goodwill Adjustment

Last Modified by ambri

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3093552	67349	5/13/2022	5/13/2022	4YDT31822L7246590		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	3/6/2020

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved

5218749

Component Model:

Component Serial Number: N 19 15

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B Cause: KEYSTONE RECAL ON LP REGULATOR Correction: REPLACED LP REGULATOR WITH NEW ONE AND PREFORMED DROP TEST (DeKing-KRV)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & subLet 28.75
 Submitted labor & subLet 75.00
 Submitted freight: 0.00
 Tax: 0.00
 Total Submitted: 103.75

Approved parts & subLet 28.75
 Approved labor & subLet 75.00
 Approved freight: 0.00
 Tax: 0.00
 Total approved: 103.75