



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67363
Promised Date: 28 MAY 22

CUSTOMER WORK ORDER

WO #: 67363

Customer: 52193 - SPIEHLER, MARK -
812-319-2757

Tag:
Author: P.HUNT

Location: 0527 CHECK PREAUTH

Stock #: 10995

Stock Desc: 2022 TT COACHMEN APEX
265RBSS

Chassis #: 5ZT2CXSB1NS042985

Serial #: 5ZT2CXSB1NS042985

Mileage: 0

Licence:

Invoice #:

Date In: 07 MAY 22

Promised: 28 MAY 22

Date Sched:

Completed: 26 MAY 22

Warr. Date: 21 JAN 22

Job #1 - Internal

COMPLAINT: SPOTS OF GLUE (FOOTPRINTS) FROM PREVIOUS WALL REPAIR ON FLOOR

CAUSE: remove glue from floor

CORRECTION: took mineral spirits and a rag and removed glue spots on the floor

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CEILING LIGHT ABOVE KITCHEN IS FLASHING

CAUSE: BJ CALLED CUSTOMER TO SEE WHICH LIGHT IS HAVING THE ISSUE. DIDNT SEE ANY FLASHING ON ANY OF THE LIGHTS IN THE CAMPER. 5/11/22

VERIFIED WHICH LIGHT IS FLASHING. WAITING ON PARTS AND APPROVAL.

CORRECTION: removed faulty light. tagged and put in parts room. installed new light and secured to ceiling.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	30.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
C01297663	4.5 INCH LED LIGHT	1.00	3.38	3.38

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-LIGHT	1.00	15.99	15.99

Subtotal for Job #2: 49.37

Job #3 - Warranty

COMPLAINT: SHOWER DOOR TRACK AT BOTTOM IS LEAKING WATER



Customer #: 52193
SPIEHLER, MARK





CAUSE: SHOWER SURROUND WAS NOT SEALED AT ALL FROM FACTORY.

CORRECTION: APPLIED SILICONE TO INSIDE AND OUTSIDE OF SHOWER SURROUND TRACK AND IN BOTH CORNERS

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		ZMS	30.00
Parts				
Part #	Description	Qty	Price	Total
500627	SILICONE - N PLUS - CLEAR	1.00	17.86	17.86
Subtotal for Job #3:				47.86

Job #22V243 - Warranty

COMPLAINT: RECALL 22V243 LP QUICK CONNECT

CAUSE: unit is not equipped with a quick connect

CORRECTION: no correction

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		ZMS	15.00
Subtotal for Job #22V243:				15.00

Job #4 - Warranty

COMPLAINT: AC IS NOT RUNNING PROPERLY. WILL ONLY RUN FOR A SHORT TIME THEN KICK OFF BEFORE THE TEMP GETS TO THE SET TEMP.

CAUSE: thermostat is dropping temp very fast and is shutting down the a/c before thr room reaches desired temp. the room sensor is located inside the shroud of the a/c. pulled shroud off and the divider was not sealing properly and allowing cold air to blow through and is hitting the room sensor.

CORRECTION: taped up divider with aluminum tape to cover all the gaps. pulled room sensor as far away from the divider as i could. ran a/c to test. thermostat is reading ambient air as it should.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		ZMS	120.00
Subtotal for Job #4:				120.00

Parts Total:	21.24
Labour Total:	195.00
Sublet Total:	0.00
Extras Total:	15.99
WORK ORDER TOTAL:	232.23

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 May 2022

