

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b> 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	<b>CLAIM STATUS</b> Authorized <b>CLAIM</b> 1058144 <b>CLAIM ORIGIN</b> WEB <b>ORIGINAL CLAIM ID</b> <b>VIN</b> 5ZT2CAVB3NX024693 <b>CHASSIS VIN</b> <b>MILEAGE</b> 0 <b>SITE/WAREHOUSE</b> 205 / 205 <b>ITEM #</b> ACAT303RKDSLE <b>DEALER RO #</b> 67415 <b>CLAIM START DATE</b> 05/23/2022 <b>CLAIM END DATE</b> 01/01/1900
<b>Labor rate:</b> \$150.00 <b>OWNER INFORMATION</b> DENNIS A SUTTON 2317 JULIANNE CR Newburgh, IN 47630 USA	<b>Retail Date of Purchase</b> 05/20/2022 <b>WARRANTY EXPIRATION DATE</b> 05/20/2023

## Claim Line Details

### Labor

Line# 1

**Operation Code**

70-147-24-00-001769

**Operational Description**

TV Coax Cable - Appliances/Television/Repair/No Tread Code

**Complaint, Cause, Correction**

Original Note : bhoffman@americanrvcenter.com, 2022-05-23 17:15:37 :: OUT SIDE TV DOES NOT GET ANY CHANNELS PULLED COAXIL CONNECTIONS FROM INSIDE AND OUTSIDE. TRACED DOWN THE COLOR OF WIRES FOUND THAT THE RIGHT SIDE COAXIL IS A SATALITE CONNECTION NOT AN OUTSIDE TV CONNECTION. LABEL THE RIGHT SIDE AS SATALITE CONNECTION AND THE LEFT AS CABLE

**Model #**

**Dlr Sub Hrs**

0.50

**Sub Labor Amt** \$75.00

**Serial #**

**Appr Hrs**

0.20

**Appr Labor Amt** \$30.00

### Notes

<b>Submitted</b>	Labor Amt	\$75.00
	Parts & Freight	\$0.00
	Total	\$75.00

<b>Approved</b>	Labor Amt	\$30.00
	Parts & Freight	\$0.00
	Total	\$30.00

DEALER \_\_\_\_\_ DATE \_\_\_\_\_

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_

SIGNATURE

All repairs described have been inspected and are satisfactory.