



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73825
Promised Date:
04 AUG 26



WO #: 73825 (Appointment Date: 05 AUG 2026 - Time: 10:15am)

Customer Name: 11927 - ROYBAL,
GUSTAVO A

Completed Date:

Invoice#:

Author: BRIAN

Stock Desc: 9428 2025 OPEN RANGE
322RLS

Serial#: 58TBM0BT3S3AG3058

Date In: 05 AUG 26

Chassis#: 58TBM0BT3S3AG3058

Time In:

Miles/Hrs:

Tag#: 7365

Purchased Date: 17 JUL 26

Warranty Date: 17 JUL 26

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES FRONT CLOSET DOORS DO NOT SLIDE SMOOTHLY. HAVE TO PICK UP DOORS

CAUSE: Closet doors dont close have to pick them up

CORRECTION: Upon inspection the screws that are suspend to be the stop for the end of the track are not properly placed causing the door to be thought to open and close ,need to remove screws and place them on the bottom track preventing door from opening and coming dismounted . Adjusting the door stops should definitely help the said issue .apply smooth pressure underneath the door latch when pushing .85HRS

Labor

Job #	Description	Total
1	CLOSET DOORS	N/C
Subtotal for Job #1:		0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES DRIVER FRONT COMPARTMENT DOOR (INVERTER) LOOSE ON HINGES AND MUST PICK UP DOOR TO CLOSE

CAUSE: Compartment door does not close properly

CORRECTION: Compartment door hinge is no longer tight and has came loose causing the hinge mechanism to no longer work properly when shutting door as-well as causing the door to be loose causing it to rub and catch on the door frame hence customer said u cant close door unless you lift it up and in .need to order new compartment door see pics for info . Will require me to remove screws holding door frame in place and then cut away silicon adhesive securing it to the body .once old door is removed need to scrape away old silicon and clean area with adhesive remover to ensure no marking left behind from old silicon . Once surface is cleaned we can re install new door with screws to hold in place then we can seal the outside edge of compartment door frame with new silicon .
1.5HRS

Labor

Job #	Description	Total
2	COMPARTMENT DOOR	N/C

Customer #: 11927
ROYBAL, GUSTAVO A





Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CUSTOEMR STATES SEWER CARRIER DOOR FELL OFF IN TRANSIT

CAUSE: NO SIGNE OF DAMAGE

CORRECTION: INSTALL REPLACEMENT END DOOR
 .10HRS

Labor

Job #	Description	Total
3	SEWER CARRIER	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES PASSENGER FENDERSKIRT CRACKED

CAUSE: SCREWS TOO TIGHT

CORRECTION: REMOVE AND REPLACE FENDERSKRIT
 .30HRS

Labor

Job #	Description	Total
4	FENDERSKIRT	N/C

Subtotal for Job #4: 0.00

Job #5 - External

COMPLAINT: CUSTOMER STATES INSTALL VENT COVER OVER BATHROOM VENT/FAN ASSEMBLY / THIS MAY REQUIRE THE BIGGER VENT COVER

CORRECTION: INSTALLED

Labor

Job #	Description	Total
5	INSTALL VENT COVER	91.00

Parts

Part #	Description	Qty	Price	Total
22-0207	FAN MATE ROOF VENT COVER, BLACK	1.00	112.10	112.10

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	4.78	4.78

Subtotal for Job #5: 207.88

Job #6 - External

CUSTOMER STATES INSTALL REPLACEMENT LP VALVE (ROUND) COVER

Subtotal for Job #6: 0.00



W/O: 73825
Promised Date: 21 AUG 26

Parts Total:	112.10
Labour Total:	91.00
Sublet Total:	0.00
Extras Total:	4.78
Tax Total:	15.85
WORK ORDER TOTAL:	223.73

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 10 Aug 2026



Customer #: 11927
ROYBAL, GUSTAVO A

