

GE Appliances - RVAC Data Information Page

Email completed form to service@mwss-inc.com

Form Date:	6-1-22	Form Rev:	2
Dealer Name:	American RV center	RV Manufacture:	Key Stone
Dealer Account Number:		Coach Make & Model:	Springdale
Dealer Phone #:	812 8675200	Year of coach:	2021
Dealer Contact Name:	Ben Hoffman	Last Eight of RV VIN:	M3110422
Dealer email:	BHoffman@AmericanRVcenter	Date of Purchase:	6-19-21
Dealer PO# / Ref #:	67441	Customer Name:	John Russell
Outdoor Unit - Model #:	ARCL5AA CBL2	Outdoor Unit - Serial #:	A5131871R
Indoor Assembly - Model #:		Indoor Assembly - Serial #:	
Electronic Control - Model #:		Electronic Control -Serial #:	
Wall Thermostat - Model #:		Wall Thermostat - Serial #:	N/A
After running unit for 15 minutes, air dump open:	84	RV Descriptions...	
Outdoor Temp. (F):	86	RV Type:	5 W
Indoor Temp. (F):	86	RV Length (ft.):	35 FT
Indoor Discharge Temp. (F):	84	# of A/Cs on RV:	1

Problem description:

Compressor is turning on. Running at 9-10 amps. Not cooling.



GE APPLIANCES

Troubleshooting/Testing Information Section - Data Required

Indoor Unit Failure:	Describe Defect Found -
Outdoor Unit Failure:	Describe Defect Found -
Fan Motor Defective:	Resistance Value - Describe Defect Found -
Compressor Defective:	Compressor resistance - Compressor amps - 8-10 Amps Describe Defect Found -
Thermistor Defective:	Indoor or Outdoor - Resistance Value - Describe defect found -
Fan Motor Capacitor:	Describe defect found -
Compressor Capacitor:	Describe defect found -
If a Refrigerant leak is found in the Sealed System, Describe the location of the Leak below:	
Condenser:	
Evaporator:	
Connecting Tubing:	
List Parts Requested:	
1.	7.
2.	8.
3.	9.
4.	10.
5.	11.
6.	12.