

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 67442
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 44907 - GARY SCHULTZ
Address: 8821 GRANT LN BRIDGEPORT, IL

62417

Phone: 618-945-9208

Stock Number: 10741 - 2022 FREEDOM EXPRESS 321FEDSLE 5ZT2FEXB8NW021807

VIN: 5ZT2FEXB8NW021807 HIN: SER#: 5ZT2FEXB8NW021807

Mileage: 0

Work Order Comp: 25 MAY 22

Auth. No:

Dealer #:

Warr. Date: 07 MAR 22

Work Order Date: 16 MAY 22

Inv #: 377409

WO #	Job #	Description	JOB INFORMATION

67442	1	FIREPLACE BREAKER NOT MAKING GOOD CONTACT FIREPLACE BREAKER NOT MAKING GOOD CONTACT. Checked fireplace operation. Not working. Checked breaker. Can push on breaked and fireplace will come on. Removed front panel that covers breakers. Checked fireplace breaker and found wire to breaker was not in wire socket. Breaker screw was tight but wire not in place. Removed breaker from panel in order to loosen tight screw. Remounted breaker and inserted wire in socket. Tightened screw. Checked operation of fireplace. Now working OK. Remounted front panel that covers breakers.	
67442	2	TOP OF DINETTE SEAT NOT ATTACHED, CAP ON TOP LOOSE TOP OF DINETTE SEAT NOT ATTACHED, CAP ON TOP LOOSE. All staples have pulled out. Removed top cap. Pulled out all old staples. Restapled inner seat back to frame. Reattached top cap. Filled all staple holes with matching putty.	
67442	3	ENTRY DOOR TO BEDROOM SCREEN DOOR HINGE SCREWS ARE STRIPPED ENTRY DOOR TO BEDROOM SCREEN DOOR HINGE SCREWS ARE STRIPPED. Checked screen door to rear bedroom. All hinge screws are stripped and will not hold screen door to hinges. Replaced all hinge screws with larger screws.	
67442	4	FRESH WATER FILL LINE AT TANK LEAKING RIGHT WHERE CRIMP IS FRESH WATER FILL LINE AT TANK LEAKING RIGHT WHERE CRIMP IS. Removed inside covers for water pump and water tank fill hose.	

Claim : 67442

 WO # Job # Description JOB INFORMATION

 Could not find a leak in this area. Cut hole in underbelly below water tank fill hose. Filled fresh water tank until overflowing. Fill hose where it is attached to water tank started dripping. Removed hose clamp that was installed too far back from end of hose. Could not remove hose from tank fill flange. Cut hose at end of fill flange. Pulled rest of hose off. Hose did not have any sealer on it except vasoline. Added clear silicone to inside end of hose. Remounted on tank with factory hose clamp. Filled fresh water tank again to check for leak. No leak at this time. Added wood strips to edge of cutout hole in underbelly. Screwed underbelly to wood strips and covered with underbelly tape. Remounted inside covers.

67442 5 FRONT SCREEN DOOR DOES NOT ALWAYS LATCH TO ENTRY DOOR, BRACKET IS LOOSE
 FRONT SCREEN DOOR DOES NOT ALWAYS LATCH TO ENTRY DOOR. BRACKET IS LOOSE.
 Checked screen door hold back. Screws that hold screen door to exterior door are stripped. Replaced screws with larger dia. screws. screen door now opens when exterior door is opened.

67442 7 COUCH IS MOVING. CUSTOMER SAYS WOOD IS LOOSE THAT HOLDS IT IN PLACE
 COUCH IS MOVING. CUSTOMER SAYS WOOD IS LOOSE THAT HOLDS IT IN PLACE.
 Removed couch from slide out area. One block was loose. Factory only put one screw in each block. Block can spin around when screw is loose. Added another screw to each block to prevent spinning around. Also added screws to vertical pieces to secure to cleats. Replaced couch behind blocks.

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.50 150.00 75.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.50 150.00 75.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.25 150.00 37.50
 Z990 4 MISC LABOUR CODE (EXTERNAL) 1.20 150.00 180.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.10 150.00 15.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.40 150.00 60.00

Parts Total: 0.00
 Labour Total: 442.50
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 442.50

Customer Signature: _____

Date: _____

Claim : 67442

Lab Code Job# Description LABOUR Hrs Rate Total
