



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73828
Promised Date:
45 AUG 26



WO #: 73828

Customer Name: 62030 - HEIN, RACHEL Completed Date:
Invoice#:
Author: BRIAN
Stock Desc: 9582 2026 LONGITUDE
285BH
Serial#: 5ZT2LNUB2T9012223
Chassis#: 5ZT2LNUB2T9012223
Miles/Hrs:
Tag#:
Purchased Date: 01 AUG 26
Warranty Date: 15 AUG 26

Date In: 06 AUG 26
Time In:

Job #1 - Internal

COMPLAINT: DEWINTERIZE

CAUSE: Dewinterize delivery

CORRECTION: Complete
Estimated Amount: 1,000.00

Labor

Job #	Description	Total
1	DEWINTERIZE/FLUSH	N/C

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

MAXXGARD

Estimated Amount: 995.00

Subtotal for Job #2: 0.00

Job #3 - Internal

ADD AC EST 5018

Estimated Amount: 1,467.53

Labor

Job #	Description	Total
3	A/C INSTALL PREWIRED	N/C

Subtotal for Job #3: 0.00

Job #4 - Internal

SWAP EQ

Labor

Job #	Description	Total
4	INSTALL EQUALIZER KIT	N/C

Customer #: 62030
HEIN, RACHEL



W/O: 73828
Promised Date: 15 AUG 26



Customer #: 62030
HEIN, RACHEL



Subtotal for Job #4: 0.00

Job #PDI2 - Internal

COMPLAINT: SFD NEW TT & INSTALL BATTERY - 1.5

CAUSE: Sfd delivery

CORRECTION: SFD complete

Jobs added

Labor

Job #	Description	Total
PDI2	SFD TRAVEL TRAILER	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #PDI2: 0.00

Job #01 - External

COMPLAINT: WARRANTY ITEM

CAUSE: Bent hinge stripped screws

CORRECTION: Checking the lower bunk, which has a lift for one side, found that it was hanging on the wall closest to the rear

Further examination found that the furthest rear hinge was bent the screws to the plywood where stripped

Remove the four screws for the hinge straightened the hinge

Reinstalled the hinge in a completely different position realigning the plywood before fully attaching the hinge tested the function of the folding portion of the bed. It is now opening and closing or standing upright and laying down correctly without dragging or hanging on the rear wall.

This job is complete

.25HRS

Labor

Job #	Description	Total
01	Lower rear bunk	1.95

Subtotal for Job #01: 1.95

Job #02 - External

COMPLAINT: WARRANTY ITEM

CAUSE: Pulled off the cabinet

CORRECTION: Found the bat strip to the left of the cabinet doors for the kitchen sink had pulled off

Pulled all the bat nails that originally held the bat strip in place

Reset the button strip back in its proper position, used to Brad nailer, nailed it back to the cabinet

Used the putty stick puttied all of the new nail holes

Job is now complete

.25HRS

Labor

Job #	Description	Total
02	Batten strip	1.95

Subtotal for Job #02: 1.95



W/O: 73828
Promised Date: 15 AUG 26

Parts Total:	0.00
Labour Total:	3.90
Sublet Total:	0.00
Extras Total:	0.00
Tax Total:	0.30
WORK ORDER TOTAL:	4.20

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 07 Aug 2026



Customer #: 62030
HEIN, RACHEL

