



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67

CUSTOMER WORK ORDER

WO #: 67489

Customer: 52650 - RANEY, DALE L. -
618-380-3363

Tag:

Author: BH

Location: 0701 CHECK PARTS

Stock #: 10836

Stock Desc: 2022 TT FOREST RIVER
CHEROKEE 274RK

Chassis #: 4X4TCKC26NX157019

Serial #: 4X4TCKC26NX157019

Mileage: 0

Licence:

Invoice #:

Date In: 20 MAY 22

Promised:

Date Sched:

Completed: 09 JUN 22

Warr. Date: 27 MAY 22

Job #FPDINTT - Internal

Transferred to BAS*67580 on 31 MAY 22

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	RAB	N/C

Subtotal for Job #FPDINTT: 0.00

Job #EQUALIZER1000 - Internal

Transferred to BAS*67580 on 31 MAY 22

Estimate amount was 0.00

INSTALL 1000# EQUALIZER HITCH

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #EQUALIZER1000: 0.00

Job #DELUXE - Internal

Transferred to BAS*67580 on 31 MAY 22

Estimate amount was 0.00

DELUXE STARTER KIT

Subtotal for Job #DELUXE: 0.00

Job #WALK - Internal

Transferred to BAS*67580 on 31 MAY 22

Estimate amount was 180.00

WALK THRU

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C



Customer #: 52650
RANEY, DALE L.



Subtotal for Job #WALK: 0.00

Job #1 - Warranty

COMPLAINT: A/C FAN WILL NOT SHUT OFF.

CAUSE: AC FAN WOULD NOT SHUT OFF DUE TO FAULTY THERMASTAT

CORRECTION: REPALCED WITH NEW THERMOSTAT AND TESTED

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	75.00

Parts				
Part #	Description	Qty	Price	Total
F100167042	THERMOSTAT HEAT/CO	1.00	37.66	37.66

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-T-STATS	1.00	15.99	15.99

Subtotal for Job #1: 128.65

Job #2 - Internal

Transferred to BAS*67580 on 31 MAY 22

Estimate amount was 0.00

GREG HELP

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: SLIDEROOM AND BLUETOOTH QUIT WORKING IN DEL AREA

CAUSE: SLIDE ROOM AND BLUETOOTH QUIT WORKING DUE TO BAD CONTROL BOARD

CORRECTION: TESTED CONTROL BOARD AND FOUND THAT THE RELAY INSIDE WAS BAD FOR THE SLIDE. I SWAPPED THE CONTROL BOARD FROM A LOT UNIT AND TESTED. NEW CONTROL BOARD WORKS. CONTROL BOARD FAILED BECAUSE THE MAIN POWER SUPPLY WIRE HAD BEEN PUSHED IN TO FAR. THE WIRES HAD BEEN CLIPPED ONTO THE WIRE INSULATION AND UNDER LOAD THE RELAY DID NOT HAD ENOUGH CONTACT ON THE WIRE. IT HEATED UP THE RELAY INSIDE AND FALED.

REPLACED CONTROL BOARD

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	N/C

Subtotal for Job #3: 0.00

Parts Total: 37.66
Labour Total: 75.00
Sublet Total: 0.00
Extras Total: 15.99
WORK ORDER TOTAL: 128.65



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 09 Jun 2022

W/O: 6/9



Customer #: 52650
RANEY, DALE L.

