

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106		CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1338440
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2FEHB8NW023099
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	320 / 320
		ITEM #	FET192RBS-320
		DEALER RO #	67494
		CLAIM START DATE	11/30/2022
		CLAIM END DATE	01/01/1900
Labor rate:	\$150.00		
OWNER INFORMATION			
WILLIAM R ANDERSON			
31 SILOAM RD			
Cadiz, KY 42211			
USA			
Retail Date of Purchase	05/27/2022	WARRANTY EXPIRATION DATE	05/27/2023

Claim Line Details

Labor
Line# 1

Operation Code

60-142-24-00-003327

Operational Description

Faucet - Plumbing/Miscellaneous Plumbing/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-11-30 16:12:32 :: CLAIM 1070540 Original Note : bhoffman@americanrvcenter.com, 2022-06-01 09:38:58 :: BATHROOM FAUCET IS CLOGGED WAS DOING A FINAL PDI TURNED ON ALL THE FAUCETS ON AT A TIME AND THE BATHROOM FAUCET DRIPPED WATER. WITH THE WATER OFF I REMOVED THE FAUCET AND TOOK PICTURES OF THE TRASH THAT WAS INSIDE THE FAUCET. RINSHED OUT THE TRASH PUT FAUCET BACK TOGETHER. TURNED ON FAUCET HOT AND COLD WORKES AS SHOULD

Model #

Serial #

Dlr Sub Hrs

Appr Hrs

0.40

0.30

Sub Labor Amt

Appr Labor Amt

\$60.00

\$45.00

Notes

Auth for .30 on claim# 1070540 which is now expired

Labor
Line# 2

Operation Code

50-134-01-00-001443

Operational Description

LP Regulator - Includes Leak Test - LP Gas/LP Gas System/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-11-30 16:13:37 :: OLD CLAIM 1070540 Original Note : bhoffman@americanrvcenter.com, 2022-06-01 09:52:35 :: THE LP REGULATOR IS NOT FUNCTIONING TRIED TO ADJUST THE LP REGULATOR FLOW, FLOW STAYED THE SAME. CHANGED OUT THE LP REGULATOR FOR A NEW REGULATOR. WORKS AS SHOULD AND FLOW WILL ADJUST TO WORK WITH FURNACE, WATER HEATER,STOVE, AND FRIDGE

Model #

Serial #

Dlr Sub Hrs

Appr Hrs

0.60

0.50

Sub Labor Amt

Appr Labor Amt

\$90.00

\$75.00

Notes

Auth for .50 on claim# 1070540 which is now expired

Labor
Line# 3

Operation Code

30-100-24-00-001046

Operational Description

Cabinet Door - Interior/Cabinetry/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-11-30 16:14:36 :: OLD CLAIM 1070540 Original Note : bhoffman@americanrvcenter.com, 2022-06-01 09:53:51 :: THE CABINET DOORS ARE LOOSE AND OPEN UP CROOKED. ADJUST AS NEEDED adjusted 5 doors to work proper

Model #

Serial #

Dlr Sub Hrs

Appr Hrs

0.40

0.40

Sub Labor Amt

Appr Labor Amt

\$60.00

\$60.00

Notes

Auth for .40 on claim# 1070540 which is now expired

Submitted

Labor Amt	\$210.00
Parts & Freight	\$0.00
Total	\$210.00

Approved

Labor Amt	\$180.00
Parts & Freight	\$0.00
Total	\$180.00

DEALER**DATE****SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER**DATE****SIGNATURE**

All repairs described have been inspected and are satisfactory.