

# Pre-Authorization

Pre-Authorization number PA03145815 Reference no: 67501 Status: Approved Approved by WillT Retail sold on Approved date 6/1/2022  
 Servicing Name Address VIN  
 Dealer

1194 Basden's American RV Basden's American RV 4YDTSGG18NW10559 5/24/2022  
 600 E Baseline Rd  
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	5101919A	Light, Clearance	0.00	0.30	0.20		1	0.20	Complaint:MARKER LIGHT DOES NOT WORK PROPERLY Cause:WIRE NOT CONNECTED Correction:WHEN TURNING ON MARKER LIGHTS ONE MARKER LIGHT WAS LIGHTING ON AND OFF. REMOVED THE MARKER LIGHT AND THE WIRE WAS BARELY HANGING ON TO THE WIRE CRIMP. REMOVED THE OLD CRIMP AND PUT NEW CRIMP IN PLACE TO COMPLETE THE CIRCUIT. TESTED THE LIGHT WORKS AS SHOULD KRV – Labor time approved in accordance with Keystone RV's flat rate manual.
2	6201106B	Regulator - Repla	0.00	0.40	0.30		1	0.30	Complaint:REGULATOR IS NOT WORKING RIGHT Cause:NOT HOLDING PRESSURE Correction:LP REGULATOR WAS NOT HOLDING, WOULD NOT RISE ABOVE 9 ON THE METER. REMOVED BAD REGULATOR AND PUT A NEW LP REGULATOR IN PLACE. DID A LP DROP TEST AGAIN, PASS LP DROP TEST KRV – Labor time approved in accordance with Keystone RV's flat rate manual. VCB: Vendor Charge Back item. (This is a Keystone RV internal notation only)
					<u>0.50</u>				

Pre-Authorization number PA03145815

For paper claims only use one pre-authorization number per warranty claim for  
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim  
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the  
 amount authorized on the pre-authorization form and return to Keystone RV Company