

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1070750
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAGC7NK003803
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	203 / 203
Labor rate:	\$150.00	ITEM #	BCAT184BHS
OWNER INFORMATION		DEALER RO #	67503
		CLAIM START DATE	06/01/2022
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description			
	60-138-01-00-001537	Black Tank No Fuss Flush Valve - Plumbing/Drainage System/Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2022-06-01 10:21:03 :: BLACK TANK FLUSH IS LEAKING ALSO IS MOUNTED SIDEWAYS REMOVED VALVE TO CHECK FOR CRACKS. I DID NOT SEE ANY CRACKS. I TESTED THE VALVE OUTSIDE THE CAMPER AND IT IS WORKING AS IT SHOULD. I CHECKED THE CONE WASHERS AND ONE SIDE LOOKED LIKE IT NEVER MADE CONTACT WITH THE VALVE. I CHANGED THE CONE WASHER AND IT DID NOT FIX THE PROBLEM. I CHANGED THE 90 DEG. FITTING AND IT STOPPED LEAKING. THEN I WAS ABLE TO PUT IT ALL BACK TOGETHER.				
	Model #	Dlr Sub Hrs	1.50	Sub Labor Amt	\$225.00
	Serial #	Appr Hrs	0.50	Appr Labor Amt	\$75.00

Notes

excessive time requested per repair description.

Labor

Line# 2	Operation Code	Operational Description			
	60-136-15-00-001499	Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2022-06-01 10:22:11 :: TOILET VALVE LEAKING REMOVED THE LINE GOING TO THE TOILET VALVE AND CHECKED THE FITTINGS. I SEEN THAT THE INSIDE CONE WASHER WAS NOT MAKING CONTACT WITH THE VALVE. I WAS ABLE TO TIGHTEN THE FITTING WITH A WRENCH AND GET THE LEAK TO STOP.				
	Model #	Dlr Sub Hrs	0.30	Sub Labor Amt	\$45.00
	Serial #	Appr Hrs	0.10	Appr Labor Amt	\$15.00

Notes

excessive time requested per repair description.

Labor

Line# 3	Operation Code	Operational Description			
	30-102-12-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2022-06-01 10:37:31 :: FIX LOWER RIGHT NOSE CAP ON THE DOOR SIDE LOWER 4 SCREWS DID NOT GO INTO ANYTHING ON THE TRIM. I REMOVED THE 4 SCREWS AND REINSTALLED THEM AT AN ANGLE. I WAS ABLE TO GET THEM TO BIT INTO SOME WOOD AND ADDED 2 SCREWS TO HELP HOLD THE TRIM DOWN.				
	Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$30.00
	Serial #	Appr Hrs	0.10	Appr Labor Amt	\$15.00

Notes

excessive time requested per repair description.

Labor
Line# 4**Operation Code**

10-11-01-00-000205

Operational DescriptionSlide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Replace/
No Tread Code**Complaint, Cause, Correction**Original Note : bhoffman@americanrvcenter.com, 2022-06-01 10:38:44 :: SLIDE ROOM SEAL ON THE FRONT
AND REAR IS FALLING DOWN I PUT THE BOLB SEALS BACK IN PLACE AND THEY FELL RIGHT OFF AGAIN.
SO I PUT THEM BACK ON AND THEN PUT A SCREW AT THE BASE TO HOLD THEM IN PLACE.**Model #****Dlr Sub Hrs**

0.30

Sub Labor Amt \$45.00**Serial #****Appr Hrs**

0.30

Appr Labor Amt \$45.00**Notes****Labor**
Line# 5**Operation Code**

60-141-19-00-001596

Operational Description

Tub Surround - Plumbing/Shower, Tub Surround/Reseal/No Tread Code

Complaint, Cause, CorrectionOriginal Note : bhoffman@americanrvcenter.com, 2022-06-01 10:39:56 :: SHOWER WALLS ARE COMING
OFF THE WALL SEALED UP AROUND SHOWER AND GLUED THE SHOWER WALL BACK ONTO THE OUTSIDE
WALL**Model #****Dlr Sub Hrs**

0.50

Sub Labor Amt \$75.00**Serial #****Appr Hrs**

0.30

Appr Labor Amt \$45.00**Notes**

excessive time requested per repair description.

Submitted

Labor Amt	\$420.00
Parts & Freight	\$0.00
Total	\$420.00

Approved

Labor Amt	\$195.00
Parts & Freight	\$0.00
Total	\$195.00

DEALER

DATE**SIGNATURE**I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER

DATE**SIGNATURE**

All repairs described have been inspected and are satisfactory.