



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVcenter.com

812.867.5200
FAX 812.868.1012

W/O: 67503
Promised Date: 28 MAY 22

CUSTOMER WORK ORDER

WO #: 67503

Customer: 52657 - RIDEOUT,
KRISTOPHER S. - 812-205-1227

Tag:

Author: BH

Location: 0536 CHECK PREAUTH

Stock #: 11028

Stock Desc: 2022 TT COACHMEN

CATALINA SUMMIT SERIES 184BHS

Chassis #: 5ZT2CAGC7NK003803

Serial #: 5ZT2CAGC7NK003803

Mileage:

Licence:

Invoice #:

Date In: 23 MAY 22

Promised: 28 MAY 22

Date Sched:

Completed: 31 MAY 22

Warr. Date: 24 MAY 22

Job #BUNKFINAL - Internal

COMPLAINT: FINAL PDI NEW BUNKHOUSE

CORRECTION: DID FINAL PDI CHECK ON CAMPER AND REPAIRED AS NEEDED.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 D	1.00	N/C	N/C

Subtotal for Job #BUNKFINAL: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CORRECTION: CLEANED UP RECEIVER ON TRUCK. INSTALLED E2 HITCH ON TRUCK AND TRAILER.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION H	1.00	N/C	N/C

Subtotal for Job #E2: 0.00

Job #BCWT - Internal

COMPLAINT: BRAKE CONTROL & WIRING - PICKUP TRUCK ONLY

CORRECTION: HELPED GREG WITH HITCHWORK
INSTALLED BRAKE CONTROL AND WIRING. USED OEM TYPE HARNESS IN THE DASH FOR THE BRAKE CONTROL. TESTED THE 7-WAY OUTPUT. HAD TO REMOVE CUSTOMERS DROP BAR FROM TRUCK RECEIVER. IT WAS RUSTED INTO THE RECEIVER AND THE DROP BAR SHOULD NOT BE USED AGAIN.

Customer #: 52657
RIDEOUT, KRISTOPHER S.





Labor				
Code	Description		Mechanic	Total
BCWT	BRAKE CONTROL & WIRING - PICKUP		GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		CAD	N/C
Parts				
Part #	Description	Qty	Price	Total
51140	PROPORTIONAL BRAKE	1.00	N/C	N/C
51383	NISSAN BRAKE CONTR	1.00	N/C	N/C
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #BCWT:				0.00

Job #WALK - Internal
 COMPLAINT: WALK THRU

CORRECTION: SET UP CAMPER IN WALK THRU AREA.DID WALK THRU SHOWED HITCH WORK AND BRAKE CONTROL.
 Estimated Amount: 180.00

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C
Subtotal for Job #WALK:			0.00

Job #1 - Warranty

COMPLAINT: BLACK TANK FLUSH IS LEAKING ALSO IS MOUNTED SIDEWAYS

CORRECTION: REMOVED VALVE TO CHECK FOR CRACKS. I DID NOT SEE ANY CRACKS. I TESTED THE VALVE OUTSIDE THE CAMPER AND IT IS WORKING AS IT SHOULD. I CHECKED THE CONE WASHERS AND ONE SIDE LOOKED LIKE IT NEVER MADE CONTACT WITH THE VALVE. I CHANGED THE CONE WASHER AND IT DID NOT FIX THE PROBLEM. I CHANGED THE 90 DEG. FITTING AND IT STOPPED LEAKING. THEN I WAS ABLE TO PUT IT ALL BACK TOGETHER.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		GAH	75.00
Parts				
Part #	Description	Qty	Price	Total
10-7150	CONE WASHER SWIVEL	1.00	0.26	0.26
72-0839	Fresh Water Adapte	1.00	2.58	2.58
Subtotal for Job #1:				77.84

Job #2 - Warranty

COMPLAINT: TOILET VALVE LEAKING

CORRECTION: REMOVED THE LINE GOING TO THE TOILET VALVE AND CHECKED THE FITTINGS. I SEEN THAT THE INSIDE CONE WASHER WAS NOT MAKING CONTACT WITH THE VALVE. I WAS ABLE TO TIGHTEN THE FITTING WITH A WRENCH AND GET THE LEAK TO STOP.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	15.00
Subtotal for Job #2:			15.00

Job #3 - Warranty

COMPLAINT: FIX LOWER RIGHT NOSE CAP ON THE DOOR SIDE



CORRECTION: LOWER 4 SCREWS DID NOT GO INTO ANYTHING ON THE TRIM. I REMOVED THE 4 SCREWS AND REINSTALLED THEM AT AN ANGLE. I WAS ABLE TO GET THEM TO BIT INTO SOME WOOD AND ADDED 2 SCREWS TO HELP HOLD THE TRIM DOWN.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	15.00
Subtotal for Job #3:			15.00

Job #4 - Warranty

COMPLAINT: SLIDE ROOM SEAL ON THE FRONT AND REAR IS FALLING DOWN

CORRECTION: I PUT THE BOLB SEALS BACK IN PLACE AND THEY FELL RIGHT OFF AGAIN. SO I PUT THEM BACK ON AND THEN PUT A SCREW AT THE BASE TO HOLD THEM IN PLACE.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	45.00
Subtotal for Job #4:			45.00

Job #5 - Warranty

COMPLAINT: SHOWER WALLS ARE COMING OFF THE WALL

CORRECTION: SEALED UP AROUND SHOWER AND GLUED THE SHOWER WALL BACK ONTO THE OUTSIDE WALL.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	22.50
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	22.50
Subtotal for Job #5:			45.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Parts

Part #	Description	Qty	Price	Total
10-0278	22753 50' 1/2" TAS	1.00	N/C	N/C
13-0115	41529 TST BLUE ENZ	1.00	N/C	N/C
40052	40052 BRASS W.P. R	1.00	N/C	N/C
5487	A10-1530HVP 15M -	1.00	N/C	N/C
13-0181	40274 2-PLY TST TO	1.00	N/C	N/C
11-0018	39741 20' RHINOFLE	1.00	N/C	N/C
Subtotal for Job #DELUXE:				0.00

Parts Total:	2.84
Labour Total:	195.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	197.84

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 01 Jun 2022

W/O: 6 713
Promis Date: 28 MAY 22



Customer #: 52657
RIDEOUT, KRISTOPHER S.



Customer Work
Order

