



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73507
Promised Date:
06 JUN 26



WO #: 73507 (Appointment Date: 06 JUN 2026 - Time: 09:15am)

Customer Name: 61640 - GONZALEZ,
AUBRY BREANN

Completed Date: 12 AUG 26

Invoice#:

Author: BRIAN

Stock Desc: 9646 2026 OPEN RANGE

COLT 17BH

Serial#: 58TBM0AJ3T7V53124

Date In: 06 JUN 26

Chassis#: 58TBM0AJ3T7V53124

Time In:

Miles/Hrs:

Tag#: 7413

Purchased Date: 18 MAY 26

Warranty Date: 18 MAY 26

Job #0 - Warranty

CLAIM: J01573206

Subtotal for Job #0: 0.00

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES CEILING PANEL SOFT AT UPPER BUNK AREA

CAUSE: Possible delamination

Damaged panel

CORRECTION: Section of ceiling needs to be replaced with a 4 x 8 sheet of roof and make sure it is the same color and design. the lights need to come down the kitchen cabinets need to be unscrewed and removed in order to fit. The skylight has to be unscrewed and come off. The cabinet where the reefer and microwave has to be unscrewed and removed. The microwave and refrigerator has to be unscrewed and removed. The new sheet has to be cut to size and all holes for the lights and skylight have to be fitted a cut. The cabinet above the dinner table also needs to be unscrewed unscrewed and removed . Once the everything is cut to size everything needs to be screwed back into its factory location fitted and tested.

Photos attached

4x8 sheet needs to be ordered

Request 5 hours

New ceiling panel arrived along with the trim strips the going between or the joint strips took measurements cut one strip to go above the microwave cabinet, which was not removed put new joint strip at the seam at the bathroom door. Attached to the ceiling joist got the new piece cut marked pilot holes drill for the ceiling vent and the light cut out. Got the ceiling panel in place got it lined up and in the new joint that was installed at it up on the ceiling and installed the second joint on the new edge, got it attached to the joist in the ceiling took measurements cut the second piece cut out the light with the new joint strip in where the air conditioner vent would be on that scene began installing the new piece on the ceiling, carefully working it into the new joint strips whats the new piece was installed center it was stapled to the ceiling joist through the middle edges were sealed with white silicone then began reinstalling all the cabinets starting with the cabinet above the dinette we got it realigned staples pulled screwed back to the wall and ceiling, reattach the shelf panel, then went to the cabinet above the kitchen sink got it realigned and some of the wiring had become disconnected from the light switches in the panel reconnected the wires that this cabinet lined up where used to be got it, reattach the wall and the ceiling reattach the panel in the base or the shelf. Reinstalled the microwave and got it reattached lined up and plugged in.

The touchup with white silicone on some of the ceiling joints how do you touch up on the new staple holes in the ceiling fan in the ceiling?

Began cleaning the tremendous mass that was left from the previous tech sawdust wood chips insulation and was on the mattresses underneath the mattresses in the shower behind the toilet underneath the

Customer #: 61640
GONZALEZ, AUBRY
BREANN





bunkbeds underneath the cushions got a shop vac vacuumed out the entire unit made sure that all this saw us. Some more chips were all cleaned out that everything was back in order unknown, where some of the personal property and what cabinets it belong in this personal property was left out for the customer to put back themselves took measurements of the damaged padded and cap for the upper bunk at 30 and three-quarter inches photo attached installed a new grease cap on the passenger side QC by Brian unit it was pulled out for pick up work complete

Labor

Job #	Description	Total
1	REPAIR CEILING PANEL	842.98

Parts

Part #	Description	Qty	Price	Total
40172	SILICONE TUBE-WHITE	1.00	13.59	13.59
0271173	TRIM, H FLAT .13 X 94.50 CEILING	3.00	2.46	7.38
2032344	WHITE PLASTIC PANEL, 2.7 X 48 X 101.38 GAUCHO 6 GA SOFT WHITE C2C	1.00	80.35	80.35

Subtotal for Job #1: 944.30

Job #1A - Internal CEILING PANELS

Parts

Part #	Description	Qty	Price	Total
2032344	PANEL, 2.7 X 48 X 101.38 GAUCHO 6 GA SOFT WHITE C2C	2.00	N/C	N/C

Subtotal for Job #1A: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES WHILE COOKING AND PAN GETS HOT THE FLAME SHUTS DOWN

CORRECTION: TESTED. COULD NOT DUPLICATE ISSUE

Labor

Job #	Description	Total
2	STOVE	0.00

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	0.00	0.00

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES DRIVER SIDE DUST CAP FELL OFF IN TRANSIT (GREASE ON WHEEL)

CAUSE: CS dust cover fell off

CORRECTION: Replaced new dust cover
 Photos attached
 .10HRS

Labor

Job #	Description	Total
3	BEARING DUST CAP INSTALL	35.80

Parts

Part #	Description	Qty	Price	Total
02823	BEARING DUST CAP W/ PLUG 2K & 3.5K AXLES	1.00	2.44	2.44



Subtotal for Job #3: 38.24

W/O: 73507
Promised Date: 06 JUN 26

Parts Total: 103.76
Labour Total: 878.78
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 982.54

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 12 Aug 2026



Customer #: 61640
GONZALEZ, AUBRY
BREANN

