



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73840
Promised Date:
11 AUG 26



WO #: 73840 (Appointment Date: 10 AUG 2026 - Time: 01:15pm)

Customer Name: 60942 - GALLEGOS,
DOLORES

Completed Date: 19 AUG 26

Invoice#:

Author: BRIAN

Stock Desc: 9599 2026 OPEN RANGE

COLT 17BH

Serial#: 58TBM0AJ6T7V53053

Date In: 10 AUG 26

Chassis#: 58TBM0AJ6T7V53053

Time In:

Miles/Hrs:

Tag#: 7369

Purchased Date: 15 NOV 25

Warranty Date: 15 NOV 25

Job #0 - Warranty

CLAIM: J01606793

Subtotal for Job #0: 0.00

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES STOVE DOES NOT STAY LIT OR LIGHT ON ITS OWN

CAUSE: The thermal couple on both burners is right up against the burner and will not allow the flame to be seen when there is a pot or a pan on the burner.

CORRECTION: I removed the two burners, the two knobs and the stove, top cover, repositioned the thermocouples to allow flame to be seen while theres a pan on the burner. This stove does not have igniters, so it will not ignite on its own by design. I had to remove the entire stove assembly in order to get the model serial number that is on the bottom of the stove pan. I reinstalled the stove reinstalled the top reinstalled the burners and the knobs. Filled a pan with water. And set on both burners one at a time to test function. Stove top now works as designed. Job completed.

.50HRS

Labor

Job #	Description	Total
1	STOVE	94.00

Subtotal for Job #1: 94.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES SHOWER LEAKING ON FLOOR / DRAINING TOWARDS KITCHEN AND ON GROUND BELOW SHOWER

CAUSE: The fittings on the P-trap came unglued

CORRECTION: I removed the access panel at the bottom of the shower and noticed the P-trap was in two pieces. I dont have access to the backside of the P-trap to remove from the shower drain. I removed all the screws out of the two end pieces, two corner pieces, and the three pieces of trim that cover the top lip of the shower surround. I pulled the shower surround up and removed the P-trap and noticed that the glue joint was barely glued together to begin with. I cleaned off all the excess glue reassembled it glued in place with ABS glue. Put the P-trap back on the bottom of the shower pan and tried to reinstall it, and thats when I see the reason why it was barely glued is because its 3/4 of an inch too tall now. I had to cut the glued pieces back apart and using my PVC drill drill out the pieces of glued in pipe from the fittings get another piece of ABS and cut the length. I dry fit everything together make sure everything would fit. When

Customer #: 60942
GALLEGOS, DOLORES



W/O: 73840
Promised Date: 11 AUG 26



Customer #: 60942
GALLEGOS, DOLORES



everything fit properly, the angle of the drain that goes through the floor wasnt gonna fit. I had to cut that pipe, fit everything together and using a rubber coupler repair the pipe that goes down through the floor. I had to scrape all the silicone off of the trim that covers the shower pan, reinstall all of those along with the corner trims and end pieces. I ran the water for five minutes down the P-trap. No leaks were noticed. Resealed the shower pan, and reinstall the access plate.
3.00HRS

Labor		
Job #	Description	Total
2	SHOWER	564.00

Parts				
Part #	Description	Qty	Price	Total
17639	1-1/2" FLEX COUPLING	1.00	6.77	6.77
40172	SILICONE TUBE-WHITE	1.00	13.59	13.59
Subtotal for Job #2:				584.36

Parts Total:	20.36
Labour Total:	658.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	678.36

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 19 Aug 2026

