



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27576



WO #: 27576

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11363

Stock Desc: 2027 TT FOREST RIVER

ROCKWOOD ULTRA 2711RK

Model: 2711RK

Serial #: 4X4TRLC23VZ203012

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 14 AUG 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: SCRATCH ON CABINET DOOR ABOVE KITCHEN SINK

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .20

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: LIVING AREA SLIDE FASCIA (BOTH SIDES AND TOP) HAS DEEP HOLES, SEVERAL AREAS ON ALL OF THEM.

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND ALL AREAS

LABOR .60

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: SCRATCH ON COUNTER TOP WHERE TV COMES UP AT

CAUSE: NOTED ON DAF

CORRECTION: BUFF AREA

LABOR .30

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: SCRATCH ON KITCHEN DOOR

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .20

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00**Job #5 - Warranty**

COMPLAINT: SCRATCH ON BEDROOM DOOR

CAUSE: NOTED ON DAF

CORRECTION: FILL AND COLOR BLEND AREAS
LABOR .20**Subtotal for Job #5: 0.00****Job #6 - Warranty**

COMPLAINT: 2 AREAS THAT ARE SCUFFED ON THE BIG CABINET IN BEDROOM

CAUSE: NOTED ON DAF

CORRECTION: FILL, SMOOTH, COLOR AND BLEND AREA
LABOR .30**Subtotal for Job #6: 0.00****Job #7 - Warranty**

COMPLAINT: SHOWER CASING ON THE RIGHT SIDE OF ENTRY TO THE SHOWER IS DAMAGED IN DIFFERENT AREAS

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE SHOWER CASING. WILL NEED TO REMOVE AND REINSTALL THE SHOWER DOORS TO PREFORM THE REPAIRS.
LABOR 2.0**Subtotal for Job #7: 0.00****Job #8 - Warranty**

COMPLAINT: THE SLIDING DOOR GOING FROM THE BATHROOM TO THE FRONT CLOSET AREA IS DAMAGED.

CAUSE: NOTED ON DAF
DAMAGED AT INSTALLCORRECTION: REPLACE THE SLIDING DOOR
LABOR .50**Subtotal for Job #8: 0.00****Job #9 - Warranty**

COMPLAINT: MATERIAL ON CORNER SECTION OF THE LIVING ROOM SEATING IS TORN IN 2 PLACES

CAUSE: TORN ON BOTTOM BLACK PART AND THE BACK TOP PART OF THE SEAT

CORRECTION: REPLACE SEATING SECTION
LABOR .50**Subtotal for Job #9: 0.00**Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

W/O: 27576

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 17 Aug 2026

Customer Signature : _____

Customer Work
Order



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

