



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27569



WO #: 27569

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11343

Stock Desc: 2027 THTT FOREST RIVER ROGUE
28L160

Model: 28L160

Serial #: 4X4TVGD29T5404211

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 12 AUG 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: SLIDING CABINET ON WALL BOTTOM PANEL COMING OFF

CAUSE: NOTED ON DAF

CORRECTION: REATTACH THE BOTTOM PANEL AND REPAIR AREA.

LABOR .30

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: RIGHT SIDE OF THE RAMP DOOR FALLS BACK WHEN YOU UNLATCH IT. AND DOOR IS NOT LINING UP CORRECTLY AS IT SHOULD.

CAUSE: NOTED ON DAF

RIGHT SIDE OF THE DOOR IS WARPED

DOES NOT LOOK LIKE THE FRAME IS DAMAGED AT THIS TIME, PLEASE NOTE FOR FURTHER POSS ISSUES.

CORRECTION: REPLACE THE RIGHT SIDE OF THE RAMP DOOR

LABOR .50

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: THERE IS A GAP IN THE OVERLAY ON THE CABINET DOOR OVER THE TV

CAUSE: NOTED ON DAF

CORRECTION: FILL AND COLOR BLEND AREA TO REPAIR ISSUE

LABOR .20

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: SCREWS ARE LOOSE AND SIDEWAYS ON THE DOOR FRAME TO THE BATHROOM FROM THE BEDROOM. THIS AREA IS SCRATCHED AS WELL.

CAUSE: NOTED ON DAF

CORRECTION: RESECURE THE SCREWS AND FILL IN THE SCRATCH.

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



LABOR .30

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: WALL IN BEDROOM IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .20

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: CORNER MOLDING IN BEDROOM LOOS UNFINISHED

CAUSE: NOTED ON DAF

CORRECTION: NEED TO FILL AND COLOR AREA TO MAKE IT BLEND BETTER

LABOR .20

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: ONE OF THE FOLD DOWN SEATS/COUCH IN THE PATIO AREA HAS A DAMAGED CUSHION PART.

CAUSE: NOTED ON DAF
CUSHION IS DAMAGED AND HAS A DEEP GROVE IN IT AND THIS AREA WILL NOT FORM BACK TO NORMAL

CORRECTION: REPLACE SEATING

LABOR 1.0

Subtotal for Job #7: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 12 Aug 2026

W/O: 27569



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

