



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27612



WO #: 27612

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11366

Stock Desc: 2027 TT KEYSTONE CROSSFIRE

245RKS

Model: 245RKS

Serial #: 4YDTBLL29VD430144

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 22 AUG 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: SCREEN MISSING ON THE FRESH WATER IN COMPARTMENT AREA

CAUSE: NOTED ON DAF

CORRECTION: REPLACE SCREEN

LABOR .20

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: LEFT SIDE OF THE RECLINER SEATING IS HITTING AGAINST THE BOTTOM FRAME AND NOT CLOSING WITHOUT A LOT OF FORCE. YOU CAN HEAR THE METAL HITTING.

CAUSE: NOTED ON DAF

CORRECTION: ADJUST THE SEATING MECH TO CLOSE CORRECTLY

LABOR .50

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: KITCHEN COUNTER HAS A HOLE BETWEEN SINK AND STOVE

CAUSE: NOTED ON DAF

CORRECTION: WILL NEED TO REPLACE THE COUNTER TOP. WILL NEED TO REMOVE AND REINSTALL THE STOVE AND KITCHEN SINK WITH FAUCET.

LABOR 4.5

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CABINET DOOR OVER SINK HAS CHIPS

CAUSE: NOTED ON DAF

CORRECTION: FILL AND COLOR BLEND AREA

LABOR .20

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00**Job #5 - Warranty**

COMPLAINT: CHIP ON THE LIVING ROOM SLIDE FASCIA

CAUSE: NOTED ON DAF

CORRECTION: FILL AND COLOR BLEND AREA

LABOR .20

Subtotal for Job #5: 0.00**Job #6 - Warranty**

COMPLAINT: DOUBLE CABINET DOORS OVER FIREPLACE ON RIGHT SIDE DON'T SHUT ALL THE WAY LIKE THE LEFT SIDE

CAUSE: NOTED ON DAF

CORRECTION: ADJUST HINGE ON RIGHT SIDE TO SHUT FLUSH AND EVENLY

LABOR .50

Subtotal for Job #6: 0.00**Job #7 - Warranty**

COMPLAINT: BATHROOM CABINET DOORS OVER SINK SCRATCHED AT BOTTOM

CAUSE: NOTED ON DAF

CORRECTION: FILL AND COLOR BLEND

LABOR .20

Subtotal for Job #7: 0.00**Job #8 - Warranty**

COMPLAINT: THE BEDROOM DOOR GOING TO THE OUTSIDE HAS A DENTED FRAME ON THE INTERIOR PART

CAUSE: NOTED ON DAF

DAMAGED/FAULTY AT FACTORY BUILD

CORRECTION: REPLACE DOOR AND FRAME

LABOR 1.0

Subtotal for Job #8: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Customer Signature : _____

Date: 22 Aug 2026

W/O: 27612



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Customer Work
Order

