



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67529

CUSTOMER WORK ORDER

WO #: 67529

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0527 CHECK PREAUTH

Stock #: 11153
Stock Desc: 2022 5W KEYSTONE
COUGAR HALF-TON 25RES
Chassis #: 4YDFCGL29NV508675
Serial #: 4YDFCGL29NV508675
Mileage: 0
Licence:

Invoice #:
Date In: 24 MAY 22
Promised:
Date Sched:
Completed: 26 MAY 22
Warr. Date:

Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CAUSE: PDI NEW FIFTH WHEEL

CORRECTION: PREFORMED PDI ON NEW FIFTH WHEEL

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	RAB	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Warranty

COMPLAINT: NO 110 VOLT IN THE CAMPER

CAUSE: CAMPER WOULD NOT GET 110 VOLTS TO THE SYSTEM DUE TO POORLY CONNECTED WIRES AT THE 110 HOOKUP OUTLER

CORRECTION: TOOK OUT OUTLET AND TIGHTENED SCREWS THAT HEL THE WIRES TOGETHER. TEHY WERE NOT TIGHT CAUSING THE WIRES NOT TO MAKE A CONNECTION

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	RAB	45.00

Subtotal for Job #1: 45.00

Customer #: 1000
BASDEN'S AMERICAN RV,



Parts Total:	0.00
Labour Total:	45.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	45.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 May 2022



Customer #: 1000
BASDENS AMERICAN RV,

