



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26941



WO #: 26941 (Appointment Date: 07 APR 2026 - Time: 09:00am)

Customer: 87620 - PARKER, ROBERT
Address: 1457 SCENIC DRIVE
NEW MARKET, TN
37820

Home Phone: (865) 850-3553

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11130

Stock Desc: 2025 FW DUTCHMEN ASTORIA
3173RLP

Model: 3173RLP

Serial #: 4YDFAAR27SZ915716

Chassis #:

Mileage:

Key #:

Req'n #: 62579

License #:

Trim:

Purchase Date: 29 DEC 25

Date In: 07 APR 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 28 APR 26

Warr. Date: 29 DEC 25

Job #1 - Warranty

COMPLAINT: UNIT HAS THE BLACK VINYL INSERT THAT IS SHRINKING

CAUSE: NON DOOR SIDE VINYL IS SHRINKING AND NOT COVERING SCREW HOLES

CORRECTION: REPLACE THE VINYL INSERT
LABOR .50

Labor

Job #	Description	Hours	Total
1	REPLACED VINYL INSERT	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
JR10061	VINYL INSERT 50' BLK	1.00	19.86	19.86

Subtotal for Job #1: 107.36

Job #2 - Warranty

COMPLAINT: ALL SLIDE SEALS ARE NOT IN THE TRACK CORRECTLY

CUST SAID THE SLIDE SEAL TRACKS ARE FULL OF SEALANT AND THAT IS NOT ALLOWING THE SEAL TO STAY IN THE TRACK AS DESIGNED TO DO

CAUSE: THE SLIDE SEALS ON ALL THREE SLIDES ARE NOT IN THE TRACKS. THIS IS DUE TO SEALANT FROM THE FACTORY IN THE TRACK NOT ALLOWING THE SEALS TO FIT PROPERLY. THE SEAL ON THE NDS HAS RIPPED AT THE TOP FROM BEING LOOSE WHEN THE SLIDE GOES IN AND OUT.

CORRECTION: NEED TO REMOVE ALL SLIDE SEALS, CLEAN SEALANT OFF TRACKS AND REPLACE WITH NEW SLIDE SEALS
THIS IS ON ALL 3 SLIDEOUTS
LABOR 3.5

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: KITCHEN CABINET DOORS AS SOON AS YOU ENTER THE UNIT NEED TO BE ADJUSTED. THE BOTTOMS OF THE CABINET DOORS ARE STICKING OUT ALOT COMPARED TO THE TOP

CAUSE: HINGES ARE OUT OF ADJUSTMENT AND ALLOWING THE CABINET DOOR TO STICK OUT AT THE BOTTOM

Customer #: 87620
PARKER, ROBERT



CORRECTION: ADJUST HINGES ON CABINET DOOR
LABOR .20

Labor

Job #	Description	Hours	Total
3	ADJUSTED CABINET HINGE	0.20	35.00

Subtotal for Job #3: 35.00

Job #4 - Warranty

THIS IS FOR LINE 2 PARTS AND LABOR
LINE IS LOCKED ON MY END

Labor

Job #	Description	Hours	Total
4	REPLACED SLIDE SEALS	3.50	612.50

Parts

Part #	Description	Qty	Price	Total
302178	BULB SEAL 1"	25.00	1.61	40.25
399358	Seal - Double Wiper - Wall Jamb	1.00	48.24	48.24

Other Services

Code	Description	Qty	Price	Total
SHP	SHP ON 302178	1.00	22.74	22.74
SHP	SHP ON 399358	1.00	51.57	51.57

Subtotal for Job #4: 775.30

Parts Total: 108.35
Labour Total: 735.00
Sublet Total: 0.00
Extras Total: 74.31
WORK ORDER TOTAL: 917.66

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 13 Aug 2026

W/O: 26941



Customer #: 87620
PARKER, ROBERT

