



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27534



WO #: 27534

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11355

Stock Desc: 2027 FW FOREST RIVER

SANDPIPER 3900HBLR

Model: 3900HBLR

Serial #: 4X4FSAR21VJ049430

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 04 AUG 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 13 AUG 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: A/C REMOTE IN LIVING ROOM AREA IS POPPING THE BACK OFF WHEN YOU REMOVE IT FROM THE HOUSING ATTACHED TO THE WALL

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE SCREWS WITH FLAT HEAD SCREWS AND RESECURE BACK IN PLACE
LABOR .20

Labor

Job #	Description	Hours	Total
1	REPAIRED AREA	0.20	35.00
Subtotal for Job #1:			35.00

Job #2 - Warranty

COMPLAINT: HIDDEN CABINET WHERE THE TV IS ON WILL NOT LATCH IN PLACE

CAUSE: NOTED ON DAF

CORRECTION: REMOVE LATCH ON WALL AND RELOCATE SO THE DOOR WILL LATCH CORRECTLY. ALSO NEED TO REMOVE THE BACK PANEL ON THE SWINGING DOOR AND SECURE THE PIN THE GOES IN THE LATCH IN PLACE.
LABOR .50

Labor

Job #	Description	Hours	Total
2	REPAIRED AREA	0.50	87.50
Subtotal for Job #2:			87.50

Job #3 - Warranty

COMPLAINT: KITCHEN CABINET DOOR HAS A SCUFF ON IT

CAUSE: NOTED ON DAF

CORRECTION: SMOOTH AREA AND COLOR BLEND TO MATCH
LABOR .20

Labor

Job #	Description	Hours	Total
3	SMOOTHED AREA AND COLOR MATCHED	0.30	52.50

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #3: 52.50

Job #4 - Warranty

COMPLAINT: KITCHEN CABINET OS PEELING AT BOTTOM AND NOT FINISHED ACROSS THE BOTTOM.THIS IS VERY VISABLE.

CAUSE: NOTED ON DAF

CORRECTION: SMOOTH AREA AND TRIM THE PAPER HANGING DOWN. COLOR BLEND AREA.
LABOR .30**Labor**

Job #	Description	Hours	Total
4	SMOOTHED AND COLOR BLENDED	0.30	52.50

Subtotal for Job #4: 52.50

Job #5 - Warranty

COMPLAINT: THERE IS A SPOT ON THE BATHROOM/LAUNDRY DOOR THAT IS LIKE A GLUE SUBSTANCE

CAUSE: NOTED ON DAF

CORRECTION: REMOVE SPOT AND COLOR BLEND THE AREA
LABOR .20**Labor**

Job #	Description	Hours	Total
5	REMOVED SPOT AND COLOR BLENDED	0.30	52.50

Subtotal for Job #5: 52.50

Job #6 - Warranty

COMPLAINT: CABINET DOORS IN THE LAUNDRY AREA ARE NOT CLOSING CORRECTLY

CAUSE: NOTED ON DAF

CORRECTION: ADJUST HINGES TO ALLOW DOORS TO CLOSE CORRECTLY
LABOR .30**Labor**

Job #	Description	Hours	Total
6	ADJUSTED HINGES	0.20	35.00

Subtotal for Job #6: 35.00

Parts Total:	0.00
Labour Total:	315.00
Sublet Total:	0.00
Extras Total:	0.00

WORK ORDER TOTAL: 315.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 13 Aug 2026

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,