



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27069



WO #: 27069

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11306

Stock Desc: 2026 FW FOREST RIVER CEDAR

CREEK 39RKB

Model: 39RKB

Serial #: 4X4FCRR24TS236101

Chassis #:

Mileage: 0

Key #:

Req'n #: 62738

License #:

Trim:

Purchase Date:

Date In: 27 APR 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 16 JUN 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: NDS REAR SLIDE SEAL IS DAMAGED AND NOT LAYING AGAINST THE SLIDE WALL

CAUSE: SLIDE SEAL DAMAGED AT INSTALL, THIS WILL ALLOW WATER AND MOISTURE IN
NOTED ON DAF

CORRECTION: REMOVE DAMAGED SLIDE SEAL, CLEAN AREA AND INSTALL A NEW SLIDE SEAL
LABOR 1.0

Labor

Job #	Description	Hours	Total
1	INSTALLED NEW SLIDE SEAL	1.50	262.50

Parts

Part #	Description	Qty	Price	Total
F100606851	SLIDE SEAL	1.00	51.16	51.16

Subtotal for Job #1: 313.66

Job #2 - Warranty

COMPLAINT: THE WINDOW SCREEN BEHIND THE DOUBLE SEATING HAS A PLACE WHERE THE
SCREEN IS DAMAGED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE WINDOW SCREEN
LABOR .50

Labor

Job #	Description	Hours	Total
2	REPLACED WINDOW SCREEN	0.10	17.50

Parts

Part #	Description	Qty	Price	Total
F100728195	SCREEN	1.00	26.60	26.60

Subtotal for Job #2: 44.10

Job #3 - Warranty

COMPLAINT: THE SHADE TO THE RIGHT OF THE KITCHEN SINK HAS WHITE MARKS ON OVER
HALF OF THE SHADE. THESE MARKS WILL NOT JUST WIPE OFF WITH A RAG

CAUSE: NOTED ON DAF

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



CORRECTION: REPLACE THE SHADE
LABOR .40

Labor

Job #	Description	Hours	Total
3	REPLACED SHADE	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
F100797646	SHADE KIT W/ SCREEN 28"X48"	1.00	126.17	126.17

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	59.46	59.46

Subtotal for Job #3: 220.63

Job #5 - Warranty

COMPLAINT: WINDOW TO THE RIGHT OF DOUBLE SEATING IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Labor

Job #	Description	Hours	Total
5	FILL COLOR AND BLEND	0.20	35.00

Subtotal for Job #5: 35.00

Job #6 - Warranty

COMPLAINT: FASCIA AROUND THE TV MANTEL IS ROUGH AND PEELING BACK

CAUSE: NOTED ON DAF

CORRECTION: SMOOTH OUT TOP WHERE IT WAS CUT AND COLOR BLEND
LABOR .20

Labor

Job #	Description	Hours	Total
6	SMOOTH TOP AND COLOR BLEND	0.20	35.00

Subtotal for Job #6: 35.00

Job #7 - Warranty

COMPLAINT: THE LINO ON THE SLIDE TO THE LEFT OF THE ENTRY DOOR IS STICKING UP IN 2 PLACES. THIS WILL NOT LAY FLAT.

CAUSE: NOTED ON DAF

CORRECTION: LINO NEEDS TO BE SECURED IN PLACE CORRECTLY
LABOR .50

Labor

Job #	Description	Hours	Total
7	SECURE LINO	0.50	87.50

Subtotal for Job #7: 87.50

Job #8 - Warranty

COMPLAINT: SEATING IN THE SITTING ROOM HAS A BLACK STAIN ON THE RIGHT CUSHION

CAUSE: NOTED ON DAF

W/O: 27069



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



CORRECTION: REPLACE THE CUSHION ON THE RIGHT SIDE
LABOR .10

Labor

Job #	Description	Hours	Total
8	REPLACED CUSHION	0.10	17.50

Parts

Part #	Description	Qty	Price	Total
F100858780	CUSHION ONLY	1.00	1,029.60	1,029.60

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON CUSHION	1.00	178.04	178.04

Subtotal for Job #8: 1,225.14

Parts Total: 1,233.53
Labour Total: 490.00
Sublet Total: 0.00
Extras Total: 237.50

WORK ORDER TOTAL: 1,961.03

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 13 Aug 2026

W/O: 27069



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

