



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27326



WO #: 27326

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11314

Stock Desc: 2026 FW FOREST RIVER

SANDPIPER 3800RK

Model: 3800RK

Serial #: 4X4FSAP22TJ049243

Chassis #:

Mileage:0

Key #:

Req'n #: 62976

License #:

Trim:

Purchase Date: 14 JUL 26

Date In: 16 JUN 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 18 AUG 26

Warr. Date: 14 JUL 26

Job #2 - Warranty

COMPLAINT: METAL IN FRONT COMPARTMENT DOOR IS SCRATCHED

CAUSE: SCRATCHED AT FACTORY BUILD, NOTED ON DAF

CORRECTION: REPLACE DAMAGED METAL IN FRONT COMPARTMENT AREA

LABOR 1.0

Labor

Job #	Description	Hours	Total
2	REPLACED METAL	1.50	262.50

Parts

Part #	Description	Qty	Price	Total
4823	METAL ON FRONT COMPARTMENT	1.00	52.00	52.00

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	108.23	108.23

Subtotal for Job #2: 422.73

Job #3 - Warranty

COMPLAINT: REAR WINDOW IS DAMAGED

GUIDE STRIP HAS CAME LOOSE AND NOT ATTACHED TO THE WINDOW AS IT SHOULD BE

CAUSE: NOTED ON DAF

DAMAGED AT BUILD

CORRECTION: REMOVE DAMAGED WINDOW AND REPLACE WITH NEW WINDOW

LABOR 1.0

Labor

Job #	Description	Hours	Total
3	REPLACED WINDOW CASE	0.40	70.00

Parts

Part #	Description	Qty	Price	Total
20X57950A	VINYL SCREEN TRACK	6.00	0.69	4.14

Subtotal for Job #3: 74.14

Job #4 - Warranty

COMPLAINT: REAR WINDOW SCREEN IS DAMAGED AND HAS A HOLE IN IT

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



CAUSE: NOTED ON DAF

CORRECTION: REPLACE REAR WINDOW SCREEN
LABOR .40**Labor**

Job #	Description	Hours	Total
4	REPLACED REAR WINDOW SCREEN	0.10	17.50

Parts

Part #	Description	Qty	Price	Total
20X67686A	WINDOW SCREEN	1.00	23.50	23.50

Subtotal for Job #4: 41.00**Job #5 - Warranty**

COMPLAINT: DAMAGE TO CABINET DOOR IN KITCHEN, STRAIGHT CHUNK IS MISSING

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20**Labor**

Job #	Description	Hours	Total
5	FILL AND COLOR	0.30	52.50

Subtotal for Job #5: 52.50**Job #6 - Warranty**

COMPLAINT: UPPER PANEL IN KITCHEN CABINET IS LOOSE FROM WALL AND THIS IS ALLOWING THE CABINET SHELF TO NOT BE STABLE

CAUSE: NOTED ON DAF
GREEN TAPE FROM FACTORY MARKING ISSUE AS WELLCORRECTION: NEED TO SECURE THE CABINET SHELF INTO CORRECT PLACE AND ALLOW IT TO REST AGAINST THE WALL AS THE OTHER ONES DO
LABOR .20**Labor**

Job #	Description	Hours	Total
6	RESECURED	0.20	35.00

Subtotal for Job #6: 35.00**Job #7 - Warranty**

COMPLAINT: STILE BESIDE THE KITCHEN CABINETS ARE STAINED IN DIFFERENT SPOTS

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND COLOR BLEND THE AREA
LABOR .20**Labor**

Job #	Description	Hours	Total
7	CLEANED AND BLENDED	0.20	35.00

Subtotal for Job #7: 35.00**Job #8 - Warranty**

COMPLAINT: KITCHEN CABINET DOORS WILL NOT SHUT LIKE DESIGNED TO DO

CAUSE: NOTED ON DAF
HINGE IS NOT IN THE CORRECT LOCATION TO ALLOW CABINET TO SHUT CORRECTLYCustomer #: 47602
TRI-AM RV CENTER-EAST
TN,

CORRECTION: ADJUST HINGES SO CABINET DOOR WILL SHUT ALL THE WAY
LABOR .30

Labor			
Job #	Description	Hours	Total
8	ADJUSTED	0.20	35.00
Subtotal for Job #8:			35.00

Job #9 - Warranty

COMPLAINT: SHADE OVER THE KITCHEN SINK IS NOT LONG ENOUGH AND DOES NOT COME ALL THE WAY DOWN COVERING THE WINDOW. TECH DID ATTEMPT TO ADJUST HOWEVER THIS DID NOT FIX THE ISSUE

CAUSE: NOTED ON DAF
WRONG SIZE SHADE WAS INSTALLED

CORRECTION: REMOVE AND REINSTALL VALANCE
REPLACE THE SHADE WITH CORRECT SIZE
LABOR .50

Labor				
Job #	Description	Hours	Total	
9	REPLACED SHADE	0.20	35.00	
Parts				
Part #	Description	Qty	Price	Total
F100802778	ROLLER SHADE	1.00	59.63	59.63
Subtotal for Job #9:				94.63

Job #10 - Warranty

COMPLAINT: STAIN/GUMMY SPOT ON KITCHEN COUNTER AND THIS WILL NOT JUST WIPE OFF.

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AREA AND BUFF COUNTER
LABOR .50

Labor				
Job #	Description	Hours	Total	
10	CLEANED AND BUFFED AREA	0.20	35.00	
Other Services				
Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	7.99	7.99
Subtotal for Job #10:				42.99

Job #11 - Warranty

COMPLAINT: KITCHEN CABINET HANDLE IS DAMAGED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE HANDLE ON CABINET
LABOR .20

Labor				
Job #	Description	Hours	Total	
11	REPLACED HANDLE ON CABINET	0.10	17.50	
Parts				
Part #	Description	Qty	Price	Total
F100617292	CABINET PULL MATTE BLACK	1.00	1.69	1.69

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Other Services

Code	Description	Qty	Price	Total
SHF	SHIPPING/FREIGHT FEE	1.00	5.00	5.00

Subtotal for Job #11: 24.19**Job #12 - Warranty**

COMPLAINT: STILE ON KITCHEN SLIDE IS CHIPPED AND PAINT FADED IN DIFFERENT AREAS

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .30

Labor

Job #	Description	Hours	Total
12	FILL AND COLOR	0.30	52.50

Subtotal for Job #12: 52.50**Job #13 - Warranty**

COMPLAINT: KITCHEN BAR IS CHIPPED AT THE BOTTOM FRONT. THIS AREA FACES THE LIVING PART OF THE UNIT.

CAUSE: NOTED ON DAF

CORRECTION: BUFF AND SMOOTH AREA

LABOR .40

Labor

Job #	Description	Hours	Total
13	BUFFED AND SMOOTH	0.40	70.00

Subtotal for Job #13: 70.00**Job #14 - Warranty**

COMPLAINT: LEFT VALANCE DOWN AT DELIVERY OVER DOUBLE SEATING

CAUSE: NOTED ON DAF
DOWN AT CHECK IN

CORRECTION: RESECURE VALANCE IN CORRECT PLACE

LABOR .20

Labor

Job #	Description	Hours	Total
14	RESECURED VALANCE	0.20	35.00

Subtotal for Job #14: 35.00**Job #15 - Warranty**

COMPLAINT: VALANCE DOWN OVER DESK IN THE LIVING AREA

CAUSE: NOTED ON DAF
DOWN AT DELIVERY

CORRECTION: RESECURE VALANCE IN CORRECT PLACE

LABOR .20

Labor

Job #	Description	Hours	Total
15	RESECURED VALANCE	0.20	35.00

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Subtotal for Job #15: 35.00

Job #16 - Warranty

COMPLAINT: VALANCE ON LIVING AREA SLIDE OUT IS DOWN

CAUSE: NOTED ON DAF

CORRECTION: RESECURE BACK INTO CORRECT PLACE

LABOR .20

Labor

Job #	Description	Hours	Total
16	RESECURED	0.20	35.00

Subtotal for Job #16: 35.00

Job #17 - Warranty

COMPLAINT: STAINS OF SOMETHING THAT WAS SPILLED DOWN THE FRONT OF THE STILE ONTO THE FLOOR

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AREA AND COLOR BLEND THE STILE WHERE IT IS STAINED

LABOR .50

Labor

Job #	Description	Hours	Total
17	CLEANED AND COLOR BLENDED AREA	0.50	87.50

Subtotal for Job #17: 87.50

Job #18 - Warranty

COMPLAINT: DRAWER UNDER TV INSTALLED SIDEWAYS, HARD TO OPEN AND CLOSE

CAUSE: NOTED ON DAF

HAREWARE WAS FOUND ON SHELF IN FRONT OF DRAWER

CORRECTION: ADJUST DRAWER GUIDE SO DRAWER IS IN CORRECTLY, OPENS AND CLOSING CORRECTLY

LABOR .40

Labor

Job #	Description	Hours	Total
18	ADJUSTED DRAWER GUIDE	0.20	35.00

Subtotal for Job #18: 35.00

Job #19 - Warranty

COMPLAINT: RIGHT OF THE ENTRY DOOR HAS EXT PAINT DULLING AND STREAKS THAT WILL NOT WIPE OFF

CAUSE: NOTED ON DAF

CORRECTION: BUFF AREAS TO BLEND ON EXT

LABOR 2.0

Labor

Job #	Description	Hours	Total
19	BUFFED AND BLENDED	0.50	87.50

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Subtotal for Job #19: 87.50

Job #20 - Warranty

COMPLAINT: ENTRY DOOR HARD TO SHUT AND DOOR IS HITTING ON BOTTOM LEFT

CAUSE: NOTED ON DAF

CORRECTION: ADJUST ENTRY DOOR TO OPERATE CORRECTLY
LABOR .50

Labor			
Job #	Description	Hours	Total
20	ADJUSTED ENTRY DOOR	0.30	52.50

Subtotal for Job #20: 52.50

Parts Total: 140.96
Labour Total: 1,085.00
Sublet Total: 0.00
Extras Total: 121.22

WORK ORDER TOTAL: 1,347.18


I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 18 Aug 2026

W/O: 27326



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

