



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27454



WO #: 27454 (Appointment Date: 28 JUL 2026 - Time: 09:00am)

Customer: 91667 - NICHOLSON, DARREN
Address: 250 EBENEZER LOOP
CHUCKEY, TN
37641

Home Phone: 423-201-5452

Work Phone:

Author: SPD

Location: IH

Invoice #:

Stock #: 11219

Stock Desc: 2026 TT FOREST RIVER

ROCKWOOD MINI 2205S

Model: 2205S

Serial #: 4X4TRLX28TD466844

Chassis #:

Mileage:

Key #:

Req'n #: 62979

License #:

Trim:

Purchase Date: 25 MAR 26

Date In: 16 JUL 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 19 AUG 26

Warr. Date: 25 MAR 26

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES COLD WATER IN BATHROOM IS LEAKING FROM UNDERNEATH THE SINK - PLEASE CHECK AND ADVISE

CAUSE: WATER LEAKING FROM COLD LINE FITTING AT FAUCET CONNECTION DUE TO A BAD SEAL.

CORRECTION: NEED TO REPLACE SEAL ON FAUCET CONNECTION
LABOR .30

Labor

Job #	Description	Hours	Total
1	REPALCED SEAL	0.30	52.50

Parts

Part #	Description	Qty	Price	Total
88-9292	SANIPRENE SWIV. SEAL 1/2"	1.00	0.35	0.35

Subtotal for Job #1: 52.85

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES ONE OF THE BLINDS BEHIND THE RECLINERS (ON THE SLIDE) JUST FELL IN THE FLOOR - PLEASE CHECK AND ADVISE

CAUSE: SHADE FABRIC IS COMING APART AT THE SEAM AND BLIND WILL NOT ROLL UP

CORRECTION: REPLACE THE SHADE
LABOR .40

Labor

Job #	Description	Hours	Total
2	REPAIRED SHADE	0.40	70.00

Subtotal for Job #2: 70.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES THEY HAVE TO MANUALLY HELP SLIDE - PLEASE CHECK AND ADVISE - STATES WORKS LIKE 7 OUT OF 10 TIMES

CAUSE: VERIFIED THE SLIDE WILL JUST CLICK WHILE TRYING TO EXTEND OUT. YOU HAVE TO THEN MANUALLY HELP SLIDE.

CORRECTION: REPLACE MOTOR ACTUATOR

Customer #: 91667
NICHOLSON, DARREN



NEED TO ACCESS THIS AREA THROUGHT HE UNDERBELLY
LABOR 1.5

Labor

Job #	Description	Hours	Total
3	REPLACED MOTOR AND ACTUATOR	1.50	262.50

Parts

Part #	Description	Qty	Price	Total
F100042930	SLIDE OUT MOTOR - 7E-1: W/ 40" ACTUATOR, 18:1 VENTURE HIGH SPEED - V# 168956	1.00	1,339.34	1,339.34

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	56.33	56.33

Subtotal for Job #3: 1,658.17

Job #4 - Warranty

COMPLAINT: UPON CHECK IN, THE BOTTOM DRAWER IN THE KITCHEN UNDER THE SINK WAS STICKING OUT, IT WOULD NOT GO BACK IN, OR PULL OUT. PLEASE CHECK AND ADVISE

CORRECTION: SCREW CAME OUT OF THE TRACK AND TECH RESECURED

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: ON JOB 2 WE WERE ASK TO TRY AND REPAIR THE SHADE AND IT WAS NOT CORRECT THE ISSUE.

CAUSE: FAULTY SHADE AND REPAIR DID NOT WORK

CORRECTION: REPLACE THE SHADE
LABOR .20

Labor

Job #	Description	Hours	Total
5	REPLACED SHADE	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
F100596330	SHADE - PFL: ROLLER NIGHT SHADE - BLACK - 39" X 24" - V# FRNB39X24RS X	1.00	52.13	52.13

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	25.59	25.59

Subtotal for Job #5: 112.72

Parts Total: 1,391.82
Labour Total: 420.00
Sublet Total: 0.00
Extras Total: 81.92
WORK ORDER TOTAL: 1,893.74

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

W/O: 27454



Customer #: 91667
NICHOLSON, DARREN



Customer Signature : _____

Date: 19 Aug 2026

W/O: 27454



Customer #: 91667
NICHOLSON, DARREN



Customer Work
Order

