



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27372



WO #: 27372

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11316

Stock Desc: 2026 TT KEYSTONE BULLET 18RBC

Model: 18RBC

Serial #: 4YDTBLH20TD431933

Chassis #:

Mileage: 0

Key #:

Req'n #: 62940

License #:

Trim:

Purchase Date:

Date In: 01 JUL 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 18 AUG 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: BATHROOM DOOR CASING IS SCRATCHED

CAUSE: NOTED ON DAF
SCRATCHED AT FACTORY

CORRECTION: REPLACE BATHROOM DOOR CASING
WILL NEED TO REMOVE THE DAMAGED CASING BEFORE INSTALL OF NEW ONE
LABOR .75

Labor

Job #	Description	Hours	Total
1	REPLACED CASING	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
641072	Trim - U-Channel - 2 7/8" x 8' - 6043-BLK - Black	1.00	5.58	5.58

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	44.23	44.23

Subtotal for Job #1: 84.81

Job #2 - Warranty

COMPLAINT: SCRATCH ON BATHROOM COUNTER TOP

CAUSE: NOTED ON DAF
SCRATCHED AT BUILD

CORRECTION: REPLACE COUNTER TOP
NEED TO REMOVE THE DAMAGED ONE BEFORE INSTALLING NEW ONE
LABOR 1.0

Labor

Job #	Description	Hours	Total
2	REPAIRED AS DIRECTED FROM KEYSTONE	0.50	87.50

Subtotal for Job #2: 87.50

Job #3 - Warranty

COMPLAINT: SLIDE FASCIA HAS MULTIPLE HOLES AND SCRATCHES FROM THE FACTORY INSTALL

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREAS ON FASCIA THAT ARE DAMAGED
LABOR 1.0

Labor

Job #	Description	Hours	Total
3	FILLED AND COLORED	0.20	35.00

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	5.99	5.99

Subtotal for Job #3: 40.99

Job #4 - Warranty

COMPLAINT: SCRATCH ON KITCHEN CABINET LEFT OF ENTRY

CAUSE: NOTED ON DAF

CORRECTION: REPLACE CABINET DOOR
LABOR .30

Labor

Job #	Description	Hours	Total
4	REPLACED CABINET DOOR	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
776536	Cabinet - Door - FPSQ - 18" x 32 1/2" - Carb 2 - 2 1/4" Side Rail - 591 Raised Cana - A-1329 - Hardwood - w/MDF Insert - Soft Maple - Paint - Urbane Bronze II	1.00	66.05	66.05

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	44.29	44.29

Subtotal for Job #4: 145.34

Job #5 - Warranty

COMPLAINT: CABINET DOOR IN KITCHEN (TOP DRAWER) SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Labor

Job #	Description	Hours	Total
5	FILLED AND COLOR BLENDED	0.20	35.00

Subtotal for Job #5: 35.00

Job #6 - Warranty

COMPLAINT: CABINET DOOR UNDER SINK SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Labor

Job #	Description	Hours	Total
6	FILLED AND COLOR BLENDED	0.20	35.00

W/O: 27372



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #6: 35.00

Job #7 - Warranty

COMPLAINT: CEILING TRIM OVER BED IS DAMAGED AND PEELING BACK

CAUSE: NOTED ON DAF

CORRECTION: SMOOTH DOWN EDGE THAT IS PEELING BACK, FILL SPACE IN TO SMOOTH OUT THE AREA
LABOR .30

Labor			
Job #	Description	Hours	Total
7	REPAIRED AREA	0.10	17.50
Subtotal for Job #7:			17.50

Job #8 - Warranty

COMPLAINT: CEILING PANEL HAS A HOLE

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .10

Labor			
Job #	Description	Hours	Total
8	FILLED AND COLOR BLENDED	0.10	17.50
Subtotal for Job #8:			17.50

Parts Total:	71.63
Labour Total:	297.50
Sublet Total:	0.00
Extras Total:	94.51
WORK ORDER TOTAL:	463.64

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 18 Aug 2026

W/O: 27372



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

