



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 6-78
Promise Date: 25 JUN 22

CUSTOMER WORK ORDER

WO #: 67538

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0628 BE SURE DKM KNOWS
THAT PARTS ARE HERE

Stock #: 11144
Stock Desc: 2022 5W KEYSTONE
COUGAR HALF-TON 24RDS
Chassis #: 4YDFCGL20NV508709
Serial #: 4YDFCGL20NV508709
Mileage: 0
Licence:

Invoice #:
Date In: 25 MAY 22
Promised: 25 JUN 22
Date Sched:
Completed: 29 JUN 22
Warr. Date: 30 JUN 22

Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CORRECTION: pdi unit

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	SAR	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	SAR	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	SAR	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	SAR	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Warranty

COMPLAINT: COMPARTMENT DOOR HOLD FOR THE SHOCK IS DAMAGED

CAUSE: COMPARTMENT DOOR HOLD FOR THE SHOCK IS DAMAGED.

CORRECTION: Removed damaged compartment door. Cleaned all old silicone from mounting surfaces. Applied thin putty tape to mounting surface on compartment door frame. Set compartment door in compartment opening. Checked for alignment. Secured frame to opening with original factory screws. Checked for opening and closing. Removed latch from damaged door and mounted on new door. Removed shock mounting brackets and mounted on new door. Applied new decal on door. Taped around new door flange and sealed with clear silicone.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	45.00
Z990	MISCELLANEOUS REPAIR	DKM	51.00
Z990	MISCELLANEOUS REPAIR	DKM	24.00

Parts

Part #	Description	Qty	Price	Total
535239	BaggageDoor-33" x 29"-Slam-Vixen-PolarWhite	1.00	201.99	201.99
5355	Diecut - 2019 - CG - Side - DC #66 - LH - FW	1.00	2.01	2.01
219210	TRAPEZOID SEAL	10.00	0.29	2.90

Customer #: 1000
BASDEN'S AMERICAN RV,





Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DECAL	1.00	11.76	11.76
FRT	FREIGHT - BAGGAGE DOOR	1.00	92.90	92.90
Subtotal for Job #1:				431.62

Job #2 - Warranty

COMPLAINT: REGULATOR DOES NOT ADJ

CORRECTION: PUT THE METER ON TO DO AN LP DROP TEST AND THE GAUGE DOES NOT MOVE FROM 8, REGULATOR WAS ALREADY MAX OUT ON ADJUSTMENT. TRIED TO ADJUST BUT DID NOT MOVE FROM 8. WILL PUT A NEW REGULATOR ON TO FIX THIS ISSUE. TURNED TANKS OFF AND REMOVE TO GET TO THE REGULATOR. REMOVED REGULATOR AND AND LINES. INSTALLED NEW REGULATOR AND THE LINES. CHECKED THE STOVE, FURNACE AND WATER HEATER ALL PERFORMED AS SHOULD, LP DROP TEST WAS ALOT BETTER.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	45.00
Z990	MISCELLANEOUS REPAIR	SAR	0.00

Parts

Part #	Description	Qty	Price	Total
59005	59005 AUTO-CHANGE OVER REGULATOR - CAMCO	1.00	69.06	69.06

Subtotal for Job #2: 114.06

Job #3 - Warranty

COMPLAINT: TOO BIG OF A STRAP ON THE LIVING ROOM TV

CORRECTION: STRAPS THAT HOLD TV INSIDE OF CABINET WAS TO LONG. CAUSING TV TO COME OUT MAKING THE STRAPS NOT FUNCTIONAL. REMOVED STRAPS FROM CURRENT LOCATION, THEN REPOSITIONED TO A DIFFERENT SPOT TO TAKE UP THE LENGTH. NOW THEY HOLD TV BACK IN CABINET AND NOT COMING OUT WHEN STRAPS ARE HOOKED.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	0.00

Subtotal for Job #3: 0.00

Parts Total: 275.96
 Labour Total: 165.00
 Sublet Total: 0.00
 Extras Total: 104.72
WORK ORDER TOTAL: 545.68

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 29 Jun 2022

