



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 27562 HOLMES, BOB

Estimate: 27562 (Appointment Date: 11 AUG 2026 - Time: 09:00am)

Customer: 52689 - HOLMES, BOB
Address: 616 OLD WITT RD
MORRISTOWN, TN
37813

Home Phone: 423-736-8430

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #:
Stock Desc: 2006 A FLEETWOOD BOUNDER
Model:
Serial #: 1F6NF53Y960A08869
Chassis #:
Mileage: 29994
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 10 AUG 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - External

CUSTOMER STATES THE COVERS ON THE TOPS OF ALL AWNINGS APPEAR TO BE SHRUNKEN AND IS ALLOWING WATER TO LEAK IN. HE IS ALSO WANTING CAULKING ON SLIDE TOPS CHECKED. HE WANTS A PRICE TO GET THEM ALL REPLACED

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00

Subtotal for Job #1: 0.00

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____

Subtotal for Job #ROOFINS: 0.00

Job #3 - External

CUSTOMER STATES THERE IS A LEAK ON THE ROOF OVER THE BED. PLEASE CHECK AND ADVISE

Subtotal for Job #3: 0.00

Job #2 - External

DOOR SIDE REAR COMPARTMENT IS DAMP ON THE ROOF CHECK AND ADVISE

Subtotal for Job #2: 0.00

Job #4 - External

CUS STATES THE BACKUP CAMERA COMES ON AND AFTER WAITING IT WILL FADE OUT CHECK AND ADVISE



Subtotal for Job #4: 0.00

Job #5 - External

THE BED SLIDE INTERMITTENTLY WORKS CHECK AND ADVISE

Subtotal for Job #5: 0.00

Job #6 - External

REAR MAX FAN IS INOP CHECK AND ADVISE

Subtotal for Job #6: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 14 Aug 2026

