

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1086625
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CANB2NU039607
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$150.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT243RBSLE
MARK J EGLI		DEALER RO #	67584
517 STEAMMILL ST PO BOX 455		CLAIM START DATE	06/09/2022
New Harmony, IN 47631		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	04/30/2022	WARRANTY EXPIRATION DATE	04/30/2023

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	40-108-24-11-001334	110 Volt Interior Wiring - Electrical/110 Volt Interior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2022-06-09 15:44:01 :: THE ELECTRICAL PLUG NEAR THE BAR IN THE KITCHEN IS NOT WORKING. ELECTRICAL PLUG AT BAR WOUND WOR, DUE TO WIRE BREAKAGE SOMWHERE IN WALL/CEILING. HOWEVER CUSTOMER WANTED UNIT BACK TODAY AND IT WILL TAKE A DAY AND A 1/2 TO FIND WIRE WIRE BREAKAGE SOMWHERE IN WALL/CEILING. HOWEVER CUSTOMER WANTED UNIT BACK TODAY AND IT WILL TAKE A DAY AND A 1/2 TO FIND WIRE. AT THIS TIME WE CANT SERVICE TILL THEY BRING IT BACK CHECKED ALL ELECTRIC 110V, HAD NOTHING AT THE BAR AND OUTSIDE PLUG. REMOVED CONVERTER AND CHECKED CONNECTIONS.CHECKED THE WIRE AT BATHROOM GCFI HAD POWER COMING IN BUT NOT OUT, THAT POWER RUNNING OUT WAS TO THE BAR AND OUTSIDE PLUG. RAN A JUNCTION BOX FROM GREEN GCFI WIRE, THEN UP TO THE BAR AND OUTSIDE PLUG. THE BAR HAS A GCFI PLUG AND THE BATHROOM HAS A NEW GCFI PLUG.THE OLD GCFI PLUG WOULD NOT TRIP IN THE BATHROOM.			
	Model #	Dlr Sub Hrs	5.00	Sub Labor Amt \$750.00
	Serial #	Appr Hrs	5.00	Appr Labor Amt \$750.00

Notes
AUTHORIZED AS REQUESTED.

Labor

Line# 2	Operation Code	Operational Description		
	60-136-01-11-001490	ShurFlo Water Pump - Plumbing/Fresh Water Supply/Replace/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2022-06-09 15:48:15 :: WHEN CUSTOMER GOT TO THE CAMPSITE THIS WEEKEND, THE WATER PUMP DID NOT WORK AT ALL. WATER PUMP WOULDNT SUCK WATER ON SUCTION SIDE INSTALLED NEW WATER PUMP			
	Model #	Dlr Sub Hrs	0.50	Sub Labor Amt \$75.00
	Serial #	Appr Hrs	0.50	Appr Labor Amt \$75.00

Notes

Submitted	Labor Amt	\$825.00	Approved	Labor Amt	\$825.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$825.00		Total	\$825.00

DEALER **DATE**

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**

SIGNATURE

All repairs described have been inspected and are satisfactory.