



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

WO #: 27604 (Appointment Date: 21 AUG 2026 - Time: 01:30pm)

Customer: 94515 - DOUBET, SAMANTHA
Address:

Home Phone: 309-251-3633

Work Phone:
Author: T.HAYES

Location: IH
Invoice #:

Stock #:
Stock Desc: 2027 TT FOREST RIVER WIKDWOOD
Model:
Serial #: 4X4TWDJ26V8813459
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 20 AUG 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - External

SC TO MAMMOTH RIDGE SITE #70
100.00 SC FEE

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #1: 0.00

Job #3 - Warranty

COMPLAINT: SHOWER IS LEAKING
THIS IS A CORNER SHOWER AND WHEN THE WATER IS ON ITS LEAKING ON THE RIGHT SIDE.

CAUSE: VERIFIED THERE IS WATER LEAKING FROM THE SHOWER AREA WHEN THE WATER HITS
THE REAR SHOWER SURROUND.

CORRECTION: SEAL AROUND SHOWER TO STOP THE WATER FROM LEAKING ONTO THE FLOOR
WHEN USING THE SHOWER.
LABOR .20

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: ENTRY DOOR IS VERY HARD TO SHUT CUST HAS TO SLAM IT.

CAUSE: TECH VERIFIED THE ENTRY DOOR IS EXTREMELY HARD TO CLOSE.

CORRECTION: ADJUST THE ENTRY DOOR TO CLOSE CORRECTLY AND AS DESIGNED
LABOR .50

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: SHELF IN BEDROOM IN MAIN CLOSET IS BROKEN AND HAS BEEN SINCE PURCHASE
OF THE UNIT

CAUSE: VERIFIED TOP SHELF IS BROKEN.

CORRECTION: REPLACE THE COMPLETE SHELF IN CLOSET
LABOR 1.0

W/O: 27604

Customer #: 94515
DOUBET, SAMANTHA

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: 2 WINDOWS IN THE LIVING ROOM 1 BEHIND COUCH AND ONE AT THE DINING TABLE HAS LEAKED DURING THE LAST RAIN. CUST STATED THERE IS A WATER HOOK UP AND HOSE TO SHOWER THE WINDOW FOR WARRANTY

CORRECTION: MAKING NOTE ON VIN WITH FOREST RIVER FOR THESE WINDOWS. TECH STATED THE WATER IS NOT ENTERING THE UNIT WHEN SHOWERING WITH WATER.

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: THE CEILING IN THE OUTDOOR KITCHEN IS COMING DOWN. CUST WILL SHOW TECH EXACTLY WHERE

CAUSE: VERIFIED THE CEILING PART OF THE OUTSIDE KITCHEN IS COMING DOWN AND NOT SECURE.

CORRECTION: RESECURE THE TOP CEILING PANEL
LABOR .30

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: BEHIND THE KITCHEN STOVE THERE IS A BLACK PIECE THAT IS SAGGING IN THE MIDDLE. CUST WILL SHOW TECH

CAUSE: VERIFIED THE BLACK PIECE RIGHT BEHIND THE STOVE IS BOWING UP AND NOT LAYING LIKE IT SHOULD

CORRECTION: REPLACE THE PIECE BEHIND THE STOVE WITH A NEW ONE AND SECURE IN PALCE
LABOR .50

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: SHADE OVER COUCH WILL NOT LOCK DOWN AND STAY WHENPULLING SHADE DOWN TO COVER WINDOW

CAUSE: FAULTY SHADE AND WILL NOT WORK AS DESIGNED TO

CORRECTION: REPLACE SHADE
LABOR .40

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: THE BACK SPLASH BEHIND THE STOVE IS BUBBLING OUT FROM THE WALL AND NOT FLUSH ON THE WALL

CAUSE: ADHESIVE ON THE BACK OF THE BACK SPLASH IS NOT STICKING AND ALLOWING BACK SPLASH TO COME LOOSE

CORRECTION: ADD DOUBLE SIDED STICKY TAPE TO BACK SPLASH AND RESECURE BACK ON WALL
LABOR .40

W/O: 27604



Customer #: 94515
DOUBET, SAMANTHA



Subtotal for Job #10: 0.00

W/O: 27604

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 26 Aug 2026



Customer #: 94515
DOUBET, SAMANTHA



Customer Work
Order

