

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
BASDEN RV CENTER INC		<b>CLAIM</b>	1087902
DBA AMERICAN RV CENTER		<b>CLAIM ORIGIN</b>	WEB
600 E BASELINE ROAD		<b>ORIGINAL CLAIM ID</b>	
EVANSVILLE, IN 47725		<b>VIN</b>	5ZT2CAVB2MX022786
USA		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$150.00	<b>SITE/WAREHOUSE</b>	205 / 205
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	ACAT303RKDSLE
HOWARD M TINGLE JR		<b>DEALER RO #</b>	67611
162 ADAM LANE		<b>CLAIM START DATE</b>	06/10/2022
Madisonville, KY 42431		<b>CLAIM END DATE</b>	01/01/1900
USA			
<b>Retail Date of Purchase</b>	08/16/2021	<b>WARRANTY EXPIRATION DATE</b>	08/16/2022

## Claim Line Details

**Labor**

**Line# 1**

<b>Operation Code</b>	60-141-02-00-001615	<b>Operational Description</b>
		Shower Door - Plumbing/Shower, Tub Surround/Adjust/No Tread Code
<b>Complaint, Cause, Correction</b>		
Original Note : bhoffman@americanrvcenter.com, 2022-06-10 11:18:51 :: SHOWER DOOR IS HANGING UP WHEN SLIDING FOUND A LOOSE ROLLER SCREW. I HAD TO REMOVE THE SHOWER DOOR AND UPPER TRACK. AFTER REMOVING GLASS DOORS AND TRACK, I REMOVED THE TRACK FROM THE DOORS. I WAS ABLE TO TIGHTEN THE SCREWS ON THE DOOR ROLLERS AND PUT IT BACK TOGETHER.		
<b>Model #</b>	<b>Dlr Sub Hrs</b>	0.25
<b>Serial #</b>	<b>Appr Hrs</b>	0.20
	<b>Sub Labor Amt</b>	\$37.50
	<b>Appr Labor Amt</b>	\$30.00

**Notes**  
AUTHORIZED AS REQUESTED.

**Labor**

**Line# 2**

<b>Operation Code</b>	40-106-24-11-001253	<b>Operational Description</b>
		Exterior 12 Volt Wiring - Electrical/12 Volt Exterior/Repair/Electrical
<b>Complaint, Cause, Correction</b>		
Original Note : bhoffman@americanrvcenter.com, 2022-06-10 11:20:59 :: FLAP UNDER TRAILER NEAR KITCHEN WITH LOOSE WIRES HANGING THERE SEALED UP ACCESS FLAP.		
<b>Model #</b>	<b>Dlr Sub Hrs</b>	0.60
<b>Serial #</b>	<b>Appr Hrs</b>	0.50
	<b>Sub Labor Amt</b>	\$90.00
	<b>Appr Labor Amt</b>	\$75.00

**Notes**  
EXCESSIVE AMOUNT REQUESTED. ADJUSTED TO TYPICAL REPAIR TIME BASED UPON REPAIR DESCRIPTION.

**Labor**

**Line# 3**

<b>Operation Code</b>	30-102-12-00-001096	<b>Operational Description</b>
		Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code
<b>Complaint, Cause, Correction</b>		
Original Note : bhoffman@americanrvcenter.com, 2022-06-10 11:25:40 :: WOOD TRIM AT THE TOP OF THE BEDROOM FIREPLACE IS BOWED NAILED DOWN THE TRIM IN THE BEDROOM AND FOUND THAT THE BATHROOM DOOR JAM HAD COME UNGLUED FROM THE WALL. I REGLUED THE DOOR JAM AND CLAMPED IT TO LET THE GLUE DRY.		
<b>Model #</b>	<b>Dlr Sub Hrs</b>	0.10
<b>Serial #</b>	<b>Appr Hrs</b>	0.10
	<b>Sub Labor Amt</b>	\$15.00
	<b>Appr Labor Amt</b>	\$15.00

**Notes**

<b>Submitted</b>	Labor Amt	\$142.50
	Parts & Freight	\$0.00
	Total	\$142.50

<b>Approved</b>	Labor Amt	\$120.00
	Parts & Freight	\$0.00
	Total	\$120.00

---

<b>DEALER</b>	<b>DATE</b>
---------------	-------------

**SIGNATURE**  
I certify that I have performed these repairs consistent with Forest River Policies.

---

<b>CUSTOMER</b>	<b>DATE</b>
-----------------	-------------

**SIGNATURE**  
All repairs described have been inspected and are satisfactory.