



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67
Promis Date: 25 JUN 22

CUSTOMER WORK ORDER

WO #: 67611

Customer: 17590 - TINGLE, JR.,
HOWARD M. - 270-584-4248

Tag:

Author: P.HUNT

Location: 0613 CHECK PREAUTH

Stock #: 10683

Stock Desc: 2021 TT COACHMEN
CATALINA 303RKDSLE

Chassis #: 5ZT2CAVB2MX022786

Serial #: 5ZT2CAVB2MX022786

Mileage:

Licence:

Invoice #:

Date In: 03 JUN 22

Promised: 25 JUN 22

Date Sched:

Completed: 13 JUN 22

Warr. Date: 19 AUG 21

Job #1 - Internal

COMPLAINT: FRIDGE NOT COOLING

CORRECTION: I PLUGED IN THE CAMPER AND CHECKED POWER. I TURNED ON THE FRIDGE WITH THE WALL SWITCH. I CHECKED THE DIAL IN THE FRIDGE AND IT WAS ONLY SET AROUND 20 PERCENT. I SET IT ON THE COLDEST SETTING. I LET THE FRIDGE RUN FOR 4 DAYS AND CHECKED IT EVERY DAY. THE FREEZER WAS HOLDING AT 0 DEG. AND THE FRIDGE WAS HOLDING AT 36-37 DEG. AFTER TESTING. I TURNED OFF THE FRIDGE AND BATTERY SHUT-OFF.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SHOWER DOOR IS HANGING UP WHEN SLIDING

CORRECTION: FOUND A LOOSE ROLLER SCREW. I HAD TO REMOVE THE SHOWER DOOR AND UPPER TRACK. AFTER REMOVING GLASS DOORS AND TRACK, I REMOVED THE TRACK FROM THE DOORS. I WAS ABLE TO TIGHTEN THE SCREWS ON THE DOOR ROLLERS AND PUT IT BACK TOGETHER.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	30.00

Subtotal for Job #2: 30.00

Job #3 - Warranty

COMPLAINT: FLAP UNDER TRAILER NEAR KITCHEN WITH LOOSE WIRES HANGING THERE

CORRECTION: SEALED UP ACCESS FLAP.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	75.00

Subtotal for Job #3: 75.00



Customer #: 17590
TINGLE, JR., HOWARD M.



Job #4 - Internal

COMPLAINT: BATTERY SEEMS TO NOT BE CHARGING WHEN DRIVING OR WHEN PLUGGED IN

~~CORRECTION: I CHECKED THE CHARGE AT THE BATTERY AND THE 7-WAY ON THE TRAILER. THE BATTERY IS CHARGING THE WAY IT SHOULD. THE 7-WAY IS CHARGING AS IT SHOULD. CUSTOMER MIGHT HAVE A BAD FUSE ON TRUCK.~~

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Subtotal for Job #4:			0.00

Job #5 - Warranty

COMPLAINT: WOOD TRIM AT THE TOP OF THE BEDROOM FIREPLACE IS BOWED

CORRECTION: NAILED DOWN THE TRIM IN THE BEDROOM AND FOUND THAT THE BATHROOM DOOR JAM HAD COME UNGLUED FROM THE WALL. I REGLUED THE DOOR JAM AND CLAMPED IT TO LET THE GLUE DRY.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	15.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Subtotal for Job #5:			15.00


Parts Total:	0.00
Labour Total:	120.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	120.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 13 Jun 2022

Customer Signature : _____



Customer #: 17590
 TINGLE, JR., HOWARD M.

