



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27637



WO #: 27637

Customer: 70622 - COUCH, PATRICK
Address: 6719 ARMS RD
WISE, VA
24293
Home Phone: 276-393-9145
Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #:
Stock Desc: 2024 FOREST RIVER CEDAR CREEK
377BH
Model: 377BH
Serial #: 4X4FCRP29RS233383
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 27 AUG 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - Warranty

COMPLAINT: SLIDE OUT IS LEAKING WATER IN DUE TO SLIDE SEAL IS TORN.

CAUSE: SLIDE SEAL TEARS AND ALLOWS WATER IN BECAUSE OF THE SLIDE OUT OPENING NOT CUT CORRECTLY. THIS IS NOT ALLOWING THE SLIDE TO GO IN AND OUT WITHOUT DAMAGING THE SEALS. THERE IS TOO MUCH OF A DIFFERENCE IN THE MEASUREMENTS FOR JUST AN ADJUSTMENT TO CORRECT THIS ISSUE. THE UNIT IS OUT OF WARRANTY HOWEVER, THE ISSUE IS FROM A INCORRECT BUILD OF THE UNIT IN THIS AREA.

CORRECTION: DISCONNECT ANY ELEC OUTLETS IN THE SLIDE OUT. REMOVE THE SLIDE OUT TO ACCESS THE AREA. TAKE MEASUREMENTS AND MARK THE AREAS THAT WILL NEED TO BE CUT TO CORRECT SIZE FOR SLIDE TO GO IN AND OUT CORRECTLY WITHOUT DAMAGING THE SEALS. REMOVE AND REPLACE THE INSIDE PANELS. REPLACE THE SLIDE OUT SEALS.
LABOR 14.0

Customer #: 70622
COUCH, PATRICK

Subtotal for Job #1: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00



I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 27 Aug 2026

