



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73488-1
Promised Date:
04 SEP 26



WO #: 73488-1

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date: 29 AUG 26

Invoice#:

Author: ADVISOR

Stock Desc: 9721 2027 R-POD

UN-MAPPED 26ML

Serial#: 037145

Chassis#: 4X4TUMB24VB037145

Miles/Hrs:

Tag#:

Purchased Date: 28 AUG 26

Warranty Date: 28 AUG 26

Date In: 15 JUL 26

Time In:

Job #01 - Warranty

COMPLAINT: TANK SENSOR NOT READING

CAUSE: Faulty sensors

CORRECTION: Unscrewed two propane, gas blocks one for the quick disconnect and one for a splitter for multiple appliances. Move them out of the way remove the screws that I had previously put into the bottom board to put it back up and use an air chisel to remove more nails to gain further access to the gray tank and the sensor locations.

Pull the bottom board down to a point to make it reasonably accessible without cutting the bottom board Place the light in the bottom board so I can see clearly one sensor at a time drilled the hole next to the old sensor place the new sensor and tighten the packing nut cut the wire away from the old sensor connected a new terminal connector which is a crimp style to each individual wire reattached it. This was done one wire at a time one drill hole at a time until all sensors have been reattached reconnected

Once this was complete, I took a water hose inside the unit to the kitchen drain filled the gray tank so that I could monitor the progress as the tank filled as a tank filled went from emptied to 1/3 2/3 then to full once reaching full, I allowed the water to sit in the gray tank for a period of time got underneath, checked each one of the new sensors that have been installed to ensure that they were sealed correctly and not leaking. None of the sensors were Leaking and then hold the lever to drain the gray tank and monitor the monitor panel inside as it went from full to 2/3 to 1/3 to empty sensors are not working correctly.

And then resecured the bottom board back in place with self drilling screws with flat washers, reattached each of the propane blocks back to the frame, got a canister of foam spray resealed all areas that have been pulled down with foam spray to ensure that they were completely sealed

QC by Jeanette work is complete

Labor

Job #	Description	Total
01	MULTIPLE LABOR CODES	798.00

Parts

Part #	Description	Qty	Price	Total
90M24147A	TANK PROBE	4.00	0.99	3.96
17150	SPRAY FOAM, KRAKEN BOND (BLACK)	1.00	14.01	14.01

Subtotal for Job #01: 815.97

Customer #: 1000
MYERS "RV" CENTER,
INC.,



W/O: 73488-1
Promised Date: 01 SEP 26

Parts Total:	17.97
Labour Total:	798.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	815.97

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 29 Aug 2026



Customer #: 1000
MYERS "RV" CENTER,
INC.,

