



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27629



WO #: 27629

Customer: 93152 - CULBERTSON, ROBERT
Address: PO BOX 262
NORTON VA
24273
Home Phone: (276) 219-9555
Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11126
Stock Desc: 2025 TT KZ-RV CONNECT SE
211MKSE
Model: 211MKSE
Serial #: 4EZTL2320S4046550
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 28 APR 26
Date In: 26 AUG 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date: 28 APR 26

Job #1 - Warranty

COMPLAINT: LEFT SIDE OF THE RECLINER CUP HOLDER IS STILL STAYING ON ALL THE TIME.
THIS IS AFTER WE REPLACE A VIB MOTOR ON KZ0041437 AND THE CUP HOLER AND HARNESS
ITSELF ON KZ0044852.

CAUSE: FAULT IN THE CUP HOLDER AND WIRING THAT WAS REPLACE ON CLAIM KZ0044852.

CORRECTION: REPLACE THE CUP HOLDER AND WIRING HARNESS
LABOR .50

Subtotal for Job #1: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 93152
CULBERTSON, ROBERT



Customer Signature : _____

Date: 26 Aug 2026

