

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106  
**BASDEN RV CENTER INC**  
 DBA AMERICAN RV CENTER  
 600 E BASELINE ROAD  
 EVANSVILLE, IN 47725  
 USA

## CLAIM STATUS



CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 5ZT2CANB1NU039954  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 103 / 103  
 ITEM # CAT243RBSLE  
 DEALER RO # 67809  
 CLAIM START DATE 06/25/2022  
 CLAIM END DATE 01/01/1900

Labor rate: \$150.00

### OWNER INFORMATION

DAVID A. SHADOWEN  
 170 N POOLE RD  
 Madisonville, KY 42431  
 USA

Retail Date of Purchase 05/07/2022      WARRANTY EXPIRATION DATE 05/07/2023

## Claim Line Details

### Labor

Line# 1      Operation Code 60-141-12-00-001560      Operational Description P-Trap - Plumbing/Shower, Tub Surround/Resecure or Tighten/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : bhoffman@americanrvcenter.com, 2022-06-25 16:39:21 :: SHOWER LEAKS UNDER THE SHOWER PAN AND ALSO WILL NOT DRAIN SHOER LEAKS AND WOULDNT DRAIN DUE TO CONNECTIONS NOT BEING TIGHT AND SEAL BEING LOSE BLOCKING DRAIN PATH TIGHTEN LINES AND REPOSTIONED SEAL AND TESTED

Model #	Dlr Sub Hrs	1.00	Sub Labor Amt	\$150.00
Serial #	Appr Hrs	0.30	Appr Labor Amt	\$45.00

**Notes**  
 EXCESSIVE AMOUNT REQUESTED. ADJUSTED TO TYPICAL REPAIR TIME BASED UPON DESCRIPTION

### Labor

Line# 2      Operation Code RC-026-01-00-004186      Operational Description 22V243, 2022-181 - FLEXTech QUICK DISCONNECTS - REMEDY (INCLUDES INSPECTION) - Recall/LP Gas System/Replace/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : bhoffman@americanrvcenter.com, 2022-06-25 16:42:03 :: RECALL 22V243 LP QUICK CONNECT RECALL ON 22V243 LP QUICK DISCONNECT INSTALLED NEW LP QUICK DISCONNECT AND TETSTED

Model #	Dlr Sub Hrs	0.30	Sub Labor Amt	\$45.00
Serial #	Appr Hrs	0.30	Appr Labor Amt	\$45.00

**Notes**

### Labor

Line# 3      Operation Code 20-46-19-00-000721      Operational Description Window - Exterior/Windows/Reseal/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : bhoffman@americanrvcenter.com, 2022-06-25 16:43:00 :: CHECK WINDOW BEHIND THE SINK FOR A LEAK. NOTICED WATER ON COUNTERTOP AFTER HARD RAIN WINDOW WAS NOT COMPLETLEY SEALED UP ON THE OUTSIDE CAUSING WATER COME IN SEALED WINDOW UP AND RAN WATER OVER IT FOR 20 MINS TO CHECK FOR LEAKS

Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$30.00
Serial #	Appr Hrs	0.10	Appr Labor Amt	\$15.00

**Notes**

EXCESSIVE AMOUNT REQUESTED. ADJUSTED TO FLAT RATE

**Labor**  
**Line# 4**

**Operation Code**

30-99-02-00-001018

**Operational Description**

Day Night Shade or Roller Shade - Interior/Soft Goods/Adjust/No Tread Code

**Complaint, Cause, Correction**

Original Note : bhoffman@americanrvcenter.com, 2022-06-25 16:43:55 :: BLINDS BEHIND THE COUCH WILL NOT GO UP OR DOWN. BLINDS BEHIND COUCH WILL NOT GO UP OR DOWN DUE TO SRINGS NOT BEING WRAPPED ARROUND HOLDER WRAPPED STRING AROUND HOLDER AND TETSTED

<b>Model #</b>	<b>Dlr Sub Hrs</b>	0.10	<b>Sub Labor Amt</b>	\$15.00
<b>Serial #</b>	<b>Appr Hrs</b>	0.10	<b>Appr Labor Amt</b>	\$15.00

**Notes**

**Submitted**

Labor Amt	\$240.00
Parts & Freight	\$0.00
<b>Total</b>	<b>\$240.00</b>

**Approved**

Labor Amt	\$120.00
Parts & Freight	\$0.00
<b>Total</b>	<b>\$120.00</b>

**DEALER**  
**SIGNATURE**

**DATE**

I certify that I have performed these repairs consistent with Forest River Policies.

**CUSTOMER**  
**SIGNATURE**

**DATE**

All repairs described have been inspected and are satisfactory.