

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
 BASDEN RV CENTER INC
 DBA AMERICAN RV CENTER
 600 E BASELINE ROAD
 EVANSVILLE, IN 47725
 USA

CLAIM STATUS Authorized
 CLAIM 1147627
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZTCFLS09NP429080
 CHASSIS VIN 1FDWE3FN9NDC20409
 MILEAGE 2199
 SITE/WAREHOUSE 210 / 210
 ITEM # FLC27QBF35
 DEALER RO # 67838
 CLAIM START DATE 07/19/2022
 CLAIM END DATE 01/01/1900

Labor rate: \$150.00

OWNER INFORMATION

CHUBBY CHOW FACTORY LLC
 7721 NEWBURGH RD
 Evansville, IN 47715
 USA

Retail Date of Purchase 03/31/2022

WARRANTY EXPIRATION DATE 03/31/2023

Claim Line Details

Labor

Line# 1

Operation Code

40-196-24-11-001297

Operational Description

Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-07-19 14:29:46 :: THE REFRIGERATOR IS NOT RUNNING. REMOVED FRIDGE FROM WALL CHECKED VOLTAGE TO FRIDGE WAS GOOD. PULL REFER, TEST REFER WITH LED AS PER SERVICE MANUAL, WHILE MOVING WIRES GET 1 FLASH, START CHECKING WIRES AS MOVING WIRE S IN UNIT BEHIND CONVERTER AC CUT OUT AND LOST ALL POWER TO REFER, REFER IS TOO BIG TO FIT THROUGH DOOR UNIT HAS NO FLOOR SPACE REFER HAS TO SIT ON FLOOR IN FRONT OF ACSES FOR FURNACE AND BACK OF CONVERTER, HAVE TO JUMP OVER SINK TO GET AROUND REFER AND ONLY HAVE LESS THAN 1FOOT SPACE TO WORK IN RUN NEW WIRE FROM REFER TO CONVERTER, TAP IN TO NEW WIRE TO POWER FURNACE CHECK AND REPAIR ELETRIC CONETIONS TYE WIRE HORNES UP IN REFER CABNET SO REFER IS NOT PLLING ON WIRE TO CONTROL PANEL AS INSTALED PUT REFER BACK IN CABNET PUT ANTIFREEZE BOTTELS IN REFER FOR TESTING,

Model #

Dlr Sub Hrs

5.00

Sub Labor Amt \$750.00

Serial #

Appr Hrs 5.00

Appr Labor Amt \$750.00

Notes

jj

Labor

Line# 2

Operation Code

30-94-15-00-004148

Operational Description

Hook or Bracket for Child Safety Net - Interior/Overhead Bunk Area/
 Repair or Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-07-19 14:32:35 :: THERE IS A CLIP MISSING ON THE OVERHEAD BUNK THAT KEEPS THE OCCUPANT FROM ROLLING OUT OF BED TOOK PICTURES OF PARTS NEEDED, SEAT BUCKLE AND STRAP. PUT IN PO FOR PARTS. installed the buckle mounts for safety net.

Model #

Dlr Sub Hrs

1.50

Sub Labor Amt \$225.00

Serial #

Appr Hrs 0.20

Appr Labor Amt \$30.00

Notes

eXCESSIVE TIME REQUEST

Labor

Line# 3

Operation Code

40-106-01-00-001258

Operational Description

Heating Pad - Holding Tank - Electrical/12 Volt Exterior/Replace/No
 Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-07-19 14:34:16 :: BLACK TANK HEATERS ARE HANGING OFF REMOVED TANK HEATER OFF OF THE BLACK TANK AND CLEANED AND INSTALLED NEW

Labor Line# 4	Model #	Dlr Sub Hrs	0.75	Sub Labor Amt	\$112.50
	Serial #	Appr Hrs	0.50	Appr Labor Amt	\$75.00
	Notes				
	eXCESSIVE TIME REQUEST				
	Operation Code	Operational Description			
	40-106-01-00-001258	Heating Pad - Holding Tank - Electrical/12 Volt Exterior/Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2022-07-19 14:36:44 :: GREY TANK HEATER FELL OFF REMOVED TANK HEATER OFF OF THE GREY TANK AND CLEANED AND INSTALLED NEW				
	Model #	Dlr Sub Hrs	0.75	Sub Labor Amt	\$112.50
	Serial #	Appr Hrs	0.50	Appr Labor Amt	\$75.00
	Notes				
	eXCESSIVE TIME REQUEST				

Submitted	Labor Amt	\$1,200.00	Approved	Labor Amt	\$930.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$1,200.00		Total	\$930.00

DEALER _____ **DATE** _____
SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE
 All repairs described have been inspected and are satisfactory.