

e-AuthOization

7/1/20
10:20:48 :

3-Authoizati number PA03176514 Reference no: 67847 Status: Approved Approved by flins Approved date 6/30/2022
rving Nae Address VIN Retail sold on

34 B-sden's American RV Basden's American RV 4YDTSGH23NW107700 5/21/2022
600 E Baseline Rd
Evansville, IN 47725

In Root je operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	6106615B Toilet - Sealand b	0.00	1.00	0.50		1	0.50	Complaint:WHEN CUSTOMER FLUSHES TOILET, IT WILL HOLD WATER FOR ABOUT 2 HOURS AND THEN THE WATER LEAKS THROUGH THE GASKET IN THE BOTTOM OF THE BOWL Cause:SEAL FOR BOWL OF TOILET ISNT HOLDING WATER. NEEDS REPLACED Correction:REMOVED ORIGINAL SEAL. INSTALLED NEW SEAL. FILLED BOWL WITH WATER AND LET SIT OVERNIGHT. TOILET SEAL IS WORKING AND IS HOLDING WATER. PARKED UNIT. KRV - Labor time approved in accordance with Keystone RV's flat rate manual.

3-Authoizati number PA03176514 0.50

r paper claims ~~only~~ use one pre-authorization number per warranty claim for
iple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the