

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
 600 E. Baseline Rd.  
 Evansville, IN  
 US  
 47725  
 812-867-5200

WARRANTY CLAIM # 67880  
 MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
 Customer: 52193 - MARK SPIEHLER  
 Address: 10215 CLUBHOUSE DR EVANSVILLE, IN

47725

Phone: 812-319-2757

Stock Number: 10995 - 2022 APEX 265RBSS 5ZT2CXSB1NS042985

VIN: 5ZT2CXSB1NS042985 HIN: SER#: 5ZT2CXSB1NS042985

Mileage: 0 Work Order Comp: 11 JUL 22

Auth. No: Dealer #:

Warr. Date: 21 JAN 22 Work Order Date: 02 JUL 22 Inv #: 379704

\*\*\*\*\*

WO #	Job #	Description	JOB INFORMATION
67880	1	WHEN OPENING THE DOOR SIDE REAR STORAGE DOOR, (GRILL AREA) THE DOOR HANGS AND CATCHES WHEN LIFTING IT UP. HINGE HAS PLASTIC END CAPS AND WAS CATCHING THE HINGE. REMOVED THE END CAPS THEN USED A FILE TO REMOVE SOME PLASTIC FOR SMOOTHER HINGING. INSTALLED THE END CAPS BACK ON HINGE. DOOR HAS NO CATCHING NO MORE	
67880	2	THE CUSTOMER CAN SET THE THERMOSTAT TO HIS DESIRED TEMPERATURE AND THE AC WILL COOL TO THAT TEMPERATURE AND KICK OFF. AFTER A WHILE, THE ROOM GETS STUFFY FEELING. ALL THE WHILE, THE AMBIENT AIR TEMP IS SHOWING 68 DEGREES IN THE CORNER OF THE T-STAT. CUSTOMER CAN TURN THE THERMOSTAT DOWN 1 DEGREE. THE AC WILL COME ON, BUT THEN THE AMBIENT AIR TEMPERATURE STARTS GOING UP. REMOVED THE COVER TO AC THEN RETAPED INSIDE OF AC, THUS KEEPING THE AIRFLOW FROM COLD SIDE BLOWING ON AIR ROOM SENSOR. THEN PUT COVER BACK ON AC . RAN AC HAD NO PROBLEMS FROM AC, FOUND NO STUFFY FEELING	

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.30	150.00	45.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.30	150.00	45.00

Parts Total: 0.00  
 Labour Total: 90.00  
 Sublet Total: 0.00  
 Extras Total: 0.00

>>>> Claim Total: 90.00

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_

Claim : 67880

```
*****  
Lab Code Job# Description LABOUR Hrs Rate Total  
*****
```