



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRV.com

812.867.5200
FAX 812.868.1012

W/O: 693
Print Date: 07 JUL 22

CUSTOMER WORK ORDER

WO #: 67893

Customer: 7923 - SISLEY, MICHAEL J. -
812-431-0995

Tag:

Author: BH

Location: 0713 CHECK PREAUTH

Stock #: 10667

Stock Desc: 2022 TT RIVERSIDE RV
RETRO 179

Chassis #: 59CCC2018NL004875

Serial #: 59CCC2018NL004875

Mileage: 0

Licence:

Invoice #:

Date In: 05 JUL 22

Promised: 07 JUL 22

Date Sched:

Completed: 11 JUL 22

Warr. Date: 07 JUL 22

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CORRECTION: FPDIT UNIT

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	SAR	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	SAR	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
40075	2 5/16" X 1 X 3" BALL	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #1 - Internal

COMPLAINT: SWAP TV AND BRACKET FROM TRADE IN

CORRECTION: REMOVED TV FROM OLD UNIT THEN INSTALLED INTO NEW UNIT. TESTED TV FOR SIGNAL.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: SWAP ALL MUD DAUBER SCREENS FROM TRADE IN

CORRECTION: SWAPED SCREENS FROM OLD TO NEW CAMPER

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: SWAP BACK UP CAMERA FROM TRADE IN



Customer #: 7923
SISLEY, MICHAEL J.

CORRECTION: REMOVED CAMERA FROM OLD UNIT THEN INSTALLED ON NEW UNIT, TRIMED WITH SILICONE

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Subtotal for Job #3:			0.00

Job #4 - Internal

COMPLAINT: SWAP SWAY BAR AND HARDWARE FROM TRADE

CORRECTION: swaped hitch and hardware from old to new camper

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Subtotal for Job #4:			0.00

Job #5 - Internal

INSTALL STEP RUGS THAT ARE ALREADY IN THE NEW PURCHASE UNIT.

Subtotal for Job #5: 0.00

Job #6 - Internal

WASH BAY TO MAXXGARD UNIT.

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: WATER HEATER HEATER CRACKED AT TOP

CORRECTION: TOP HOT SIDE OF WATER HEATER FITTING IS BROKE. REMOVED THE FITTING FROM PEX LINE,HAD TO HEAT UP A BOLT TO EXTACT THE OLD FITTING. PLACE A BRASS FITTING TO FIX THIS ISSUE. THEN FILLED WATER HEATER TO CHECK FOR LEAKS THEN THE COLD SIDE ON THE BOTTOM HAS A CRACK IN FITTING ,CAUSING WATER TO LEAK EVERYWHERE.REPLACE WITH A BRASS FITTING AS WELL. DRIANED WATER OUT OF WATER HEATER TO REPLACE FITTING.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	42.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	108.00

Parts				
Part #	Description	Qty	Price	Total
72-0818	1/2" MPT TO 1/2" PEX	2.00	2.40	4.80
Subtotal for Job #7:				154.80

Job #8 - Warranty

COMPLAINT: PANELING ON BED COMING OFF

CORRECTION: PANEL WAS NOT STAPLED WELL. RESTAPLED PANEL TOOK PICTURES

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	15.00
Subtotal for Job #8:			15.00

Job #9 - Warranty

COMPLAINT: THE TV ANTENNA IS NOT RECIEVING SIGNAL TO PICK UP CHANNELS



CORRECTION: HAD ANTENNA AMP ON GOT NO SIGNAL THEN REMOVED ANTENNA AMP AND FRIDGE TO CHECK CONNECTION. THE CABLE COAXIAL WAS HOOKED TO THE ANTENNA IN SPOT. REVERSED ALL COAXEL HOOKUPS TO THE PROPER CONNECTION TILL HAD SIGNAL ALL WORK AS SHOULD. PUT ANTENNNA AMP BACK IN PLACE ALONG WITH THE FRIDGE CHECK PICTURES

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	75.00
Subtotal for Job #9:			75.00

Job #WALK - Internal
 COMPLAINT: WALK THRU

CAUSE: DONE
 Estimated Amount: 180.00

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	VV	N/C
Subtotal for Job #WALK:			0.00

Job #10 - Internal
 COMPLAINT: INSTALL DIFFERENT DRAW BAR

CORRECTION: UNHOOKED TRAILER AND REMOVED OLD TOW BAR. REMOVED SWAY-B FROM TOW BAR. WENT OUT FRONT TO HELP DIFFERENT CUSTOMER WITH THERE HITCH. I GOT A NEW TOW BAR AND INSTALLED ALL OF THE SWAY-B STUFF AND BALL ONTO IT. INSTALLED THE NEW TOW BAR AND HOOKED UP THE TRAILER AGAIN. PULLED UNIT OUT FOR CUSTOMER.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Parts				
Part #	Description	Qty	Price	Total
45036	2IN DROP LOADED BALL MOUNT W/ 2IN BALL 7.5K W/ PIN & CLIP	1.00	N/C	N/C
Subtotal for Job #10:				0.00

Parts Total:	4.80
Labour Total:	240.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	244.80

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 11 Jul 2022

Customer #: 7923
 SISLEY, MICHAEL J.

