



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRV.com

812.867.5200
FAX 812.868.1012

W/O: 14
Promit Date: 30 JUL 22

CUSTOMER WORK ORDER

WO #: 67914

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0714 CHECK WORK

Stock #: 11231
Stock Desc: 2022 TT COACHMEN
FREEDOM EXPRESS 20SE
Chassis #: 5ZT2FEJB1NW025268
Serial #: 5ZT2FEJB1NW025268
Mileage:
Licence:

Invoice #:
Date In: 07 JUL 22
Promised: 30 JUL 22
Date Sched:
Completed: 11 JUL 22
Warr. Date:

Job #1 - Internal

COMPLAINT: PDI NEW FREEDOM EXPRESS TRAVEL TRAILER

CAUSE: PDI NEW FREEDOM EXPRESS TRAVEL TRAILER.

CORRECTION: Moved unit into shop. Filled LP tanks. Installed new battery box. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Checked roof and awning. Checked entrance door and all compartment doors. Leveled unit. Operated all stab jacks. Checked power cord. Checked all interior vlights. Checked converter output. Checked all cabinets and drawers. Checked all windows and blinds. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Recorded all serial numbers and took pictures. Applied all company decals. Added water to fresh water tank. Flushed antifreeze from water lines and faucets. Connected to city water and filled all holding tanks to check monitor panel. Performed LP drop test and set LP pressure at 10 in.wc. Operated all appliances. Checked TV Antenna, TV and Radio. Retracted all stab jacks. Drained all holding tanks, including water heater. Moved unit back to sales lot.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	8.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SUPPORT UNDER DINETTE SEAT BROKEN

CAUSE: SUPPORT UNDER DINETTE BROKEN.

CORRECTION: Removed broken cross support. Cut off old staples holding cross support. Cut new support to fit. Secured in place with angle brackets.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	60.00



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #2: 60.00

Job #3 - Warranty

COMPLAINT: REAR WINDOW BLIND WON'T STAY UP

CAUSE: REAR WINDOW BLIND WON'T STAY UP

CORRECTION: String needs tightened. Bottom anchor screw hole stripped. Shortened blind string and installed with a larger screw. Blind now stays up.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	22.50

Subtotal for Job #3: 22.50

Job #4 - Warranty

COMPLAINT: PANTRY DOOR WON'T LATCH CLOSED

CAUSE: PANTRY DOOR WON'T LATCHED CLOSED.

CORRECTION: Latch plate is not aligned with door knob plunger. Removed latch plate and remounted to align with door plunger. Door now latches closed.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	15.00

Subtotal for Job #4: 15.00

Job #5 - Warranty

COMPLAINT: GRAVITY FILL HOSE PINCHED FLAT BELOW FLOOR

CAUSE: GRAVITY FILL HOSE PINCHED FLAT BELOW FLOOR.

CORRECTION: Fill hose is between top of tank and floor. Removed clamps holding LP line. Removed tank supports to take pressure off of tank and it to drop a little. Disconnected fill hose at both ends. Pulled fill hose up thru hole in floor and removed. Inserted new fill hose down thru floor and connected to tank. Vent hose also pulled off at outside fill fitting. Hose too short. Removed outside fill and reconnected vent hose. Added a 3 inch section to vent hose to reach outside fill flange. Connected new fill hose to outside fill fitting. Line from water tank to water pump too short and is pinched flat where it connects to winterizing hose. Cut hose and added a 90 deg. fitting to eliminat pinch. Checked fill hose for leaks. Fill hose leaks at tank fitting. Resealed hose fitting and retightened. No leak. Repaired cut in underbelly made for access to tanf fitting. Remounted tank supports and secured LP line.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	225.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	225.00

Parts

Part #	Description	Qty	Price	Total
11-0186	1-3/8"x10' FLEX FILL HOSE	1.00	21.51	21.51
88-8302	BARB UNION	1.00	0.61	0.61
88-8309	BARB ELBOW 1/2 X 1/2	1.00	0.86	0.86

Subtotal for Job #5: 472.98



W/O: 674
Promise Date: 30 JUL 22

Parts Total:	22.98
Labour Total:	547.50
Sublet Total:	0.00
Extra Total:	0.00
WORK ORDER TOTAL:	570.48

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 11 Jul 2022



Customer #: 1000
BASDEN'S AMERICAN RV,

