



Warranty Authorization Form

Date: 7/19/2022

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd,
Evansville, IN 47725
Ph. (812) 867-5200

General Information

Pre-Auth #: 20483 Unit: 7M5FP4224NB201340
Series: Paradigm Model: 2022PAR385FL
Notes:
Status: Approved

Dealer Information

American RV Basden RV Center, Inc. DBA/ American RV Requestor: Ben Hoffman
(812) 867-5200 600 E Baseline Rd,
Evansville, IN 47725 Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 22432 CABINET - DRAWER GUIDE - REPAIR Fault Code: COMPONENT FAILURE
(photos required)

Serial #: Model #: Notes:

Problem: REAR DRAWER SLIDE PULLED OUT OF FLOOR ON THE DOOR SIDE SEE BEN BEFORE YOU PULL IT OUT AND I CAN SHOW YOU WHERE IT IS Time Requested: .3
Cause: SCREWS FROM THE FACTORY WERE TOO SHORT Time Allowed: .3
Remedy: TOOK OUT ALL FACTORY LITTLE SCREWS AND INSTALLED BIGGER SCREWS. Sublet Repairs: 0.00
Part Return Req: No
Status: Approved

Operation Line 2

Flat Rate Code: 20043A TERMINATION VALVES - REPLACE - (Photo of valve after removal/replace is required) Fault Code: COMPONENT FAILURE

Serial #: Model #: Notes: 7/12: Danielle -- as the flat rate code states, photo of valve is required, I need to know if this is a Bristol valve or a Valterra valve

Problem: BLACK WATER PULL WILL NOT GO BACK IN Time Requested: 2.5
Cause: FAULER OF HANDLE VALVE Time Allowed: 2.5
Remedy: TOOK UNDERBELLY DOWN AND REMOVED CABLE, SLIDE ON TANK IS GOOD, CABLE WILL NOT MOVE BACK AND FOURTH. PUT NEW CABLE BACK IN PLACE AND MOUNTED AND IT WORKS GREAT, PUT UNDERBELLY BACK IN PLACE, ALL IS GOOD. Sublet Repairs: 0.00
Part Return Req: No
Status: Approved

Operation Line 6

Flat Rate Code: 14085 TRIM - INTERIOR - REPAIR

Fault Code: COMPONENT FAILURE

Serial #:

Model #:

Notes:

Problem: THERE IS TRIM IN THE MIDDLE OF THE WALL IN THE HALF BATH THAT IS LOOSE

Time Requested: .3

Cause: LOOSE

Time Allowed: .3

Remedy: TOOK OFF STICKER TRIM AND RESTAPLED BOTH SIDES OF WALL BOARD AND REINSTALLED STICKER ON SEAM.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved