

RE: 11229 - 2022 TT RIVERSIDE RV INTREPID 165i Ser#: 59CCC481XNL005915 RO 67963

Warranty @Riverside RV <warranty@goriversiderv.com>

Thu 8/4/2022 11:41 AM

To: Ben Hoffman <bhoffman@americanrvcenter.com>

Hi Ben,

Auth.# 080422-6 for .60 hrs. labor

1 - .10 Resecure Light

2 - .30 RR Fill Hose

3 - .20 Tape



Thank you and have a good day,

Laura Kay Meyers

Warranty

Riverside RV

1775 E US 20

Lagrange, IN 46761

260-499-4578

Ext. 110

From: Ben Hoffman <bhoffman@americanrvcenter.com>

Sent: Thursday, August 4, 2022 12:07 PM

To: Warranty @Riverside RV <warranty@goriversiderv.com>

Subject: Re: 11229 - 2022 TT RIVERSIDE RV INTREPID 165i Ser#: 59CCC481XNL005915 RO 67963

UPDATE

BEN HOFFMAN

WARRANTY/SERVICE

AMERICAN RV CENTER

600 EAST BASELINE RD

EVANSVILLE, IN 47725

PH. 812-867-5200 EXT 263

FAX. 812-868-1012

EMAIL. BHOFFMAN@AMERICANRVCENTER.COM

****OUR PHONES SYSTEM DOES NOT ACTIVATE UNTIL 9 A.M. CENTRAL****

I'M NOT YELLING AT YOU. OUR SYSTEM ONLY RECOGNIZES CAPITOL LETTERS

From: Ben Hoffman

Sent: Friday, July 29, 2022 11:30 AM

To: Warranty Manager Riverside RV <warranty@goriversiderv.com>

Subject: 11229 - 2022 TT RIVERSIDE RV INTREPID 165i Ser#: 59CCC481XNL005915 RO 67963

1. BED ROOM LIGHT HANGING DOWN

- a. BEDROOM LIGHT HANGING DOWN DUE TO LOSE SCREW
- b. REATTACHED SCREW

i. LABOR .1

2. FRESH TANK LINE HAS A HOLE IN IT

- a. HOSE HAS A HOLE IN IT
- b. NEED TO REPLACE THE HOSE

i. LABOR 1.0

3. DINNETE HAS A SCRATCH ON IT

- a. DINNETE HAD SCRATCH ON IT REMOVED AND COVERED WITH WOOD TAPE
- b. REMOVED AND COVERED UP WITH WOOD TAPE

i. LABOR .4

BEN HOFFMAN

WARRANTY/SERVICE

AMERICAN RV CENTER

600 EAST BASELINE RD

EVANSVILLE, IN 47725

PH. 812-867-5200 EXT 263

FAX. 812-868-1012

EMAIL. BHOFFMAN@AMERICANRVCENTER.COM

****OUR PHONES SYSTEM DOES NOT ACTIVATE UNTIL 9 A.M. CENTRAL****

I'M NOT YELLING AT YOU. OUR SYSTEM ONLY RECOGNIZES CAPITOL LETTERS