



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67973
Promised Date: 30 JUL 22

CUSTOMER WORK ORDER

WO #: 67973 (Appointment Date: 13 JUL 2022 - Time: 07:00am)

Customer: 52740 - CORNELIUS, BRIAN Stock #: 10712

D. - 270-929-0645

Tag:

Author: P.HUNT

Location: 1104 BH TO CLOSE

Stock Desc: 2022 TT KEYSTONE

SPRINGDALE 282BH

Chassis #: 4YDTSGN28N3102613

Serial #: 4YDTSGN28N3102613

Mileage: 0

Licence:

Invoice #:

Date In: 13 JUL 22

Promised: 30 JUL 22

Date Sched:

Completed: 31 OCT 22

Warr. Date: 16 JUN 22

Job #1 - Internal

COMPLAINT: Transferred to BAS*68177 on 04 AUG 22

Estimate amount was 0.00

INSTALLING A 2ND AC PER DREW. AC UNIT IN BAY 1A

CORRECTION: bring in unit and get AC customer supplied, Dometic, M# B57915.XX1CO, S# 10892278, CHANGE FROM WHITE TO BLACK, REMOVE SEALER FROM VENT FOR BEDROOM, REMOVE VENT, USE ROOF TAPE TO COVER HOLES FROM VENT, PUT AC ON ROOF OVER HOLE, MATERESS WITH TOPPER UNDER VENT AND NO ROOM TO MOVE MATTRESS TOO, PUT COVER OVER BED, RUN 120 VOLT WIRES FROM JUNCTION BOX IN TO VENT HOLE, CUT WOOD TO CLOSE UP HOLES IN ROOF TRUSSES, TAPE UP SO AIR BOX IS TIGHT, INSTALL AC AND WIRE UP, MARK BATTING STRIP, REMOVE AIR DISTERBUTION BOX, Dometic 3314851.000, CUT BATTING STRIP AND REMOVE FOR AC, INSTALL AIR BOX, AND TEST, CLEAN UP TRASH FROM INSTATION

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: Transferred to BAS*68177 on 04 AUG 22

Estimate amount was 0.00

OFF DOOR SIDE HAS A HOLE IN FRONT ON OUTSIDE. MARKED WITH TAPE

CORRECTION: staple is not under corner molding, clean up sealer, trimming off acsess and tapeing off and cap sealing corner

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JP	N/C
Z990	MISCELLANEOUS REPAIR	JP	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: ON BUNK FABRIC IS FRAYED. MARKED WITH BLUE TAPE

CAUSE: INSTALLED FABRIC

Customer #: 52740
CORNELIUS, BRIAN D.



CORRECTION: take pics and turn PO

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR		0.00
Z990	MISCELLANEOUS REPAIR	JP	150.00

Parts

Part #	Description	Qty	Price	Total
674064	DecorDusk4" x 4 1/2"w/4"x 30 3/4" - BUNKPAD	1.00	3.52	3.52

Other Services

Code	Description	Qty	Price	Total
FRT	UPS BUNK PAD	1.00	12.54	12.54

Subtotal for Job #3: 166.06

Job #4 - Internal

COMPLAINT: Transferred to BAS*68177 on 04 AUG 22

Estimate amount was 0.00

FRONT DOOR SIDE SEALENT HAS COME LOOSE. MARKED WITH BLUE TAPE

CORRECTION: trim and cean off access loose sealer from corner

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JP	N/C

Subtotal for Job #4: 0.00

Parts Total: 3.52
Labour Total: 150.00
Sublet Total: 0.00
Extras Total: 12.54
WORK ORDER TOTAL: 166.06

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 04 Nov 2022

W/O: 67973
Promised Date: 30 JUL 22

Customer #: 52740
CORNELIUS, BRIAN D.

