

e-Authozization

8/5/20
04:38:59 PM

3-Authozization number PA03196005 Reference no: 67984 Status: Approved Approved by kiddz Approved date 7/22/2022
rving Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDFM0R28N4702082 3/10/2022
600 E Baseline Rd
Evansville, IN 47725

Item	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2300518A	Entrance Door - I-	0.00	0.20	0.20		1	0.20	Complaint:HINDGES ON THE DOOR ARE SCRAPING BLACK PAINT AND THE ALUMINUM OFF *Sent to LCI - CTS 07/20* Cause:INSTALL ISSUE Correction:TOUCHUP WITH BLACK PAINT, MARKER
2	5104303B	Receptacle 120V	0.00	1.00	0.30		1	0.30	Complaint:PLUG AT COFFEE BAR POPS OUT WHEN YOU UNPLUG IT Cause:TOOK PICTURES OF OUT THAT IS BROKEN DO TO WAS NOT SET IN PLACE PROPERLY PUT IN PO FOR WARRANTY Correction:NEED TO REPLACE THE PLUG IN
3	2300108B	Entrance Door - I-	0.00	2.50	1.30		1	1.00	Complaint:BUBBLE ON THE ENTRY DOOR ABOUT 1/2 OF THE WAY UP ON THE LEFT ON THE INSIDE Cause:TOOK PICTURE OF DOOR PUT IN PO FOR WARRANTY Correction:NEED TO REPLACE THE DOOR
3-Authozization number PA03196005					1.80				KRV - Per LCI - After reviewing this case we will approve the door replacement under warranty and 1 hour labor. Thank you.

paper claims ~~only~~ use one pre-authozization number per warranty claim for
multiple copy of this pre-authozization to a warranty claim form. Fill out the header information and the parts section on the claim
form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the