



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67984
Promised Date: 31 AUG 22

CUSTOMER WORK ORDER

WO #: 67984 (Appointment Date: 15 JUL 2022 - Time: 07:00am)

Customer: 46506 - VUKOVICH, THOMAS Stock #: 11163

J. - 812-459-0749

Tag:

Author: BJW

Location: 0808 CHECK STATUS WITH SAR

Stock Desc: 2022 5W KEYSTONE

MONTANA 3121RL

Chassis #: 4YDFM0R28N4702082

Serial #: 4YDFM0R28N4702082

Mileage:

Licence:

Invoice #:

Date In: 15 JUL 22

Promised: 31 AUG 22

Date Sched:

Completed: 31 JUL 22

Warr. Date: 10 MAR 22

Job #1 - Warranty

COMPLAINT: HINDGES ON THE DOOR ARE SCRAPING BLACK PAINT AND THE ALUMINUM OFF

CORRECTION: BEN SAID TOUCHUP WITH BLACK PAINT, MARKER

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	30.00
Z990	MISCELLANEOUS REPAIR		0.00

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DECAL & RECEIPT	1.00	11.76	11.76

Subtotal for Job #1: 41.76

Job #2 - Warranty

COMPLAINT: PLUG AT COFFEE BAR POPS OUT WHEN YOU UNPLUG IT

CAUSE: TOOK PICTURES OF OUT THAT IS BROKEN DO TO WAS NOT SET IN PLACE PROPERLY PUT IN PO FOR WARRANTY

CORRECTION: TOOK PICTURES OF OUT THAT IS BROKEN DO TO WAS NOT SET IN PLACE PROPERLY PUT IN PO FOR WARRANTY. REMOVED BAD PLUG THEN INSTALLED NEW PLUG. CHECKED THE PLUG FOR 110V.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	45.00
Z990	MISCELLANEOUS REPAIR	SAR	0.00
Z990	MISCELLANEOUS REPAIR		0.00

Parts

Part #	Description	Qty	Price	Total
S817	S817 BLACK DUAL OUTLET W/WALL COVER PLATE	1.00	9.63	9.63

Subtotal for Job #2: 54.63

Job #3 - Internal

COMPLAINT: THE LEFT LOCK OIN THE DRIVERS SIDE STORAGE COMPARTMENT WILL NOT LOCK

CORRECTION: CHECKED DOOR BY TRYING TO LOCK GOT WITH SIR BEN ABOUT THIS ISSUE WILL LUBE LOCK. IF YOU PUSH DOOR IN THEN IT WILL LOCK



Customer #: 46506
VUKOVICH, THOMAS J.



Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	N/C
Subtotal for Job #3:			0.00

Job #4 - Warranty

COMPLAINT: BUBBLE ON THE ENTRY DOOR ABOUT 1/2 OF THE WAY UP ON THE LEFT ON THE INSIDE

CAUSE: TOOK PICTURE OF DOOR PUT IN PO FOR WARRANTY

CORRECTION: TOOK PICTURE OF DOOR PUT IN PO FOR WARRANTY. REMOVED BAD DOOR PUT IN NEW DOOR TRIMED WITH SILICONE. CHANGED OUT LOCKS TO THE DOOR. ADDED NEW DECAL

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	195.00
Z990	MISCELLANEOUS REPAIR	SAR	0.00
Z990	MISCELLANEOUS REPAIR		0.00

Part #	Description	Qty	Price	Total
683004	Diecut - 2022 - MO - Side - DC #75 - RH	1.00	6.56	6.56
682857	Entrance - Door - RH - 30" x 78 1/2" - 8070R - FB - BCMH - MSTONE - ISPL - BKG - NOB - SHPBBT20 - BSCD - BKP - SA - NT - BLKSLD - DEF	1.00	596.79	596.79

Other Services

Code	Description	Qty	Price	Total
FRT	UPS FREIGHT - ENTRY DOOR	1.00	145.01	145.01
Subtotal for Job #4:				943.36

Parts Total:	612.98
Labour Total:	270.00
Sublet Total:	0.00
Extras Total:	156.77
WORK ORDER TOTAL:	1,039.75

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 Aug 2022



Customer #: 46506
 VUKOVICH, THOMAS J.

