

aim: C3166920

Non-Warranty Goodwill Adjustment

Last Modified by: ambrl

aim

Reference no.

68055

Repair start date

7/25/2022

Repair date

7/25/2022

VIN

4YDT28022M3106443

Pre-auth

1194

Dealer

Basden's American RV

Repairing dealer name

600 E Baseline Rd
Evansville, IN 47725

Labor rate

150.00

Changed Type

0.00

SA21-414

1/30/20

ny Item de number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Approved

18749

Component Model: 6020

Component Serial Number: N 20 32

ny Operation de	Description	Srv advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION: 71 COMPONENT: 414 OPERATION: 7141442B PART#380444 Cause: LP REGULATOR RECALL Correction: INSTALLED NEW LP REGULATOR AND PREFORMED DROP TEST (DeKing-KRV)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & sublet	28.75	Approved parts & sublet	28.75
Submitted labor & sublet	75.00	Approved labor & sublet	75.00
Submitted freight:	0.00	Approved freight	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	103.75	Total approved:	103.75