

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106		CLAIM STATUS		
BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA		CLAIM ORIGIN ORIGINAL CLAIM ID VIN 5ZT2CAGC4NK003399 CHASSIS VIN MILEAGE 0		
Labor rate: \$150.00		SITE/WAREHOUSE 203 / 203		
OWNER INFORMATION		ITEM # BCAT184BHS		
NORMA L SCHULTZ		DEALER RO # 68068		
10211 NORTH RD Elberfeld, IN 47613 USA		CLAIM START DATE 07/27/2022		
		CLAIM END DATE 01/01/1900		
Retail Date of Purchase 01/29/2022		WARRANTY EXPIRATION DATE 01/29/2023		

Claim Line Details

Labor

Line# 1	Operation Code RC-026-01-00-004186	Operational Description 22V243, 2022-181 - FLEXTech QUICK DISCONNECTS - REMEDY (INCLUDES INSPECTION) - Recall/LP Gas System/Replace/No Tread Code			
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-07-27 17:25:39 :: RECALL 22V243 LP QUICK CONNECT LP QUICK DISCONNECT RECALL INSTALLED NEW LP QUICK DISCONNECT AND TESTED Additional Note : bhoffman@americanrvcenter.com, 2022-07-27 17:29:58 :: TRIED TO UPLOAD PHOTOS IT WILL NOT LET ME					
	Model #	Dlr Sub Hrs	0.30	Sub Labor Amt	\$45.00
	Serial #	Appr Hrs	0.30	Appr Labor Amt	\$45.00
Notes					

Labor

Line# 2	Operation Code 20-69-01-00-000703	Operational Description Hold Back Latch, Catch, or Magnet - Exterior/Compartment Doors/ Replace/No Tread Code			
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-07-27 17:26:26 :: MAGNET MISSING DOOR SIDE FRONT FOR A COMPARTMENT DOOR magnet missing from door side front compartment. needs new one. pictures in one drive needs new magnet INSTALL NEW MAGNET					
	Model #	Dlr Sub Hrs	0.10	Sub Labor Amt	\$15.00
	Serial #	Appr Hrs	0.10	Appr Labor Amt	\$15.00
Notes					

Labor

Line# 3	Operation Code RC-029-19-00-004139	Operational Description 22V003, 2022-001 - COOKTOP INVERTED FLAME - Recall/Stove/Reseal/ No Tread Code			
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-07-27 17:27:25 :: RECALL 22V003 COOK TOP INVERTED FLAME recall on cook top inverted flame. removed microwave and found that it already had pannel and was sealed. no action required no action required					
	Model #	Dlr Sub Hrs	1.00	Sub Labor Amt	\$150.00
	Serial #	Appr Hrs	1.00	Appr Labor Amt	\$150.00

Notes

Submitted

Labor Amt	\$210.00
Parts & Freight	\$0.00
Total	\$210.00

Approved

Labor Amt	\$210.00
Parts & Freight	\$0.00
Total	\$210.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.