

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 68072
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 52399 - SCOTT TOELLE
Address: 5506 STONEPOINT DR MT VERNON, IN

47620

Phone: 812-483-1767

Stock Number: 11140 - 2022 COUGAR 316RLS 4YDFCGR24N2509449

VIN: 4YDFCGR24N2509449 HIN: SER#: 4YDFCGR24N2509449

Mileage: 0

Work Order Comp: 06 AUG 22

Auth. No:

Dealer #: 1194

Warr. Date: 17 JUN 22

Work Order Date: 26 JUL 22

Inv #: 380951

WO # Job # Description JOB INFORMATION

68072 1 DURING THE RAINS CUSTOMER NOTICED THAT WATER WAS COMING OUT OF
THE SEALS NEAR THE NOSE CAP AND HITCH.
GOT ON ROOF AND FOUND THE FRONT CAP NEEDED SEALED WITH
DICOR, FACTORY DID NOT COVER SEVERAL SPOTS, USED 2 TUBES OF DICOR
AND SEALED SKYLIGHT.

68072 5 THE PENDANT LIGHT OVER THE CENTER ISLAND FELL AND BROKE WHILE
TRAVELING.
welds broke on light need to order new light housing. INSTALLED
NEW HOUSING

68072 8 THE MOTION LIGHT ON THE STEPS COME ON AND OFF FOR NO REASON.
NEED NEW LIGHT, THERE SEEMS TO BE GLUE AND SILICONE ON IT, LOOKS
BAD. INSTALLED NEW MOTION LIGHT.

68072 20 WHEN ON WATER PUMP IT KEEPS RUNNING AND HAS A LEAK AT THE FRONT
CHECK AND ADVISE
found leak in closet to hot side for washing machine hook up, had
to take one door off and shelf out and cabinet base out and pull
out wall to get to elbow by floor, cut out elbow and reinstalled a
new elbow and clamps to repair, tested with water pressure and it
dont leak, put wall back together and bottom base and shelf and
reinstalled door, all is good.

68072 6 THE SHOWER STALL SURROUND SEEMS LOOSE AND THE CAULK SEEMS WEAK
RESEALED TOP OF SHOWER SURROUND.

Claim : 68072

```

*****
WO #      Job #      Description      JOB INFORMATION
*****
68072      7      SOME OF THE DRAWERS AND DOORS DO NOT CATCH PROPERLY
                ADJUSTED 3 DRAWERS AND REPLACED ONE CATCH.

68072      10      THERE IS AN INTERIOR TRIM PIECE AROUND THE MAIN DOOR POPPED
                LOOSE.
                TOOK OFF TRIM AND CUT TO LENGTH AND REINSTALLED.

68072      12      THE TRIM ON THE DINING SLIDE NEAREST THE ENTRY DOOR IS LOOSE.
                STAPLED TRIM BACK IN PLACE .

68072      14      THE LP HOSE DRIVER SIDE THAT GOES TO THE HARD PIPE IS HANGING
                DOWN LOW ENOUGH THAT THEY COULD BE DAMAGED BY TRAVEL AND
                ELEMENTS.
                TOOK LP TANK OUT AND USED A HOSE CLAMP TO TIE UP HOSE SO IT
                DOESN'T HANG DOWN.

68072      15      TRIM PEICES ON THE BED ROOM CLOSET OUTSIDE AND INSIDE COMING OFF
                REINSTALLED BOTH TRIM PIECES IN CLOSET AND OUTSIDE OF CLOSET.

68072      16      CABINET DOOR UNDER LEFT KITCHEN SINK COMING AWAY FROM THE CABINET
                NOTHING WRONG WITH DOOR IT JUST NEEDED ADJUSTED IN.

68072      17      DRIVER SIDE BASEMENT STORAGE DOOR HAS A GAP
                MOVED SEAL SO IT WOULD SEAL UP WITH DOOR,NO DAYLIGHT THROUGH IT
                NOW.

68072      18      KITCVHEN SLIDE SEALER IS COMING OFF OF THE TRAILER
                SEALED BOTH SIDES OF KITCHEN SLIDE ROOM AND TOP RAIL.

```

```

*****
Part No      Job#      Description      PARTS      Qty      Price      Total
*****
DCR505LSW-1      1      PW HAPS FREE SELF-LEVELING DICOR      2.00      8.64      17.28
655439      5      Light - Pendant - 12V - LED - Bla      1.00      66.01      66.01
592487      8      Light - LED - Motion Sensor - Cou      1.00      7.62      7.62
88-9503      20      UNION ELBOW 1/2"CST      1.00      6.49      6.49

```

```

*****
Lab Code      Job#      Description      LABOUR      Hrs      Rate      Total
*****
Z990      1      MISC LABOUR CODE (EXTERNAL)      0.20      150.00      30.00
Z990      5      MISC LABOUR CODE (EXTERNAL)      0.00      150.00      0.00
Z990      5      MISC LABOUR CODE (EXTERNAL)      0.20      150.00      30.00
Z990      8      MISC LABOUR CODE (EXTERNAL)      0.00      150.00      0.00
Z990      8      MISC LABOUR CODE (EXTERNAL)      0.20      150.00      30.00

```

Claim : 68072

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990      20    MISCELLANEOUS REPAIR      0.80     150.00    120.00
Z990      6     MISCELLANEOUS REPAIR      0.30     150.00     45.00
Z990      7     MISCELLANEOUS REPAIR      0.60     150.00     90.00
Z990     10    MISC LABOUR CODE (EXTERNAL)  0.10     150.00     15.00
Z990     12    MISC LABOUR CODE (EXTERNAL)  0.10     150.00     15.00
Z990     14    MISCELLANEOUS REPAIR      0.20     150.00     30.00
Z990     15    MISCELLANEOUS REPAIR      0.20     150.00     30.00
Z990     16    MISCELLANEOUS REPAIR      0.10     150.00     15.00
Z990     17    MISCELLANEOUS REPAIR      0.20     150.00     30.00
Z990     18    MISCELLANEOUS REPAIR      0.30     150.00     45.00

```

```

*****
Excode    Job#  Description      EXTRAS      Qty      Price      Total
*****
SS         1     SHOP SUPPLIES      1.00       0.00       0.00
FRT        5     UPS-LIGHTS JOBS 5,8  1.00      24.41      24.41

```

```

Parts Total:      97.40
Labour Total:     525.00
Sublet Total:       0.00
Extras Total:      24.41

```

>>>> Claim Total: 646.81

Customer Signature: _____

Date: _____